Discussion

The original survey by W. B. Barr was found to be inconsistent with the survey record approved by the Surveyor General on March 21, 1885. Previous retracements of Barr's work in this area show this inconsistency not to be unexpected—refer to Survey No. 7-44-11 and Survey Nos. 6-43-10, -11 and -12. At this point in time, no pattern has been developed as to Barr's non-conformance to the prescribed methods of survey as set forth by the GLO. As discovered in previous retracements, the major significance of Barr's inferior survey methods is the very large area that must be searched before an obliterated corner may be declared lost.

Survey performed by:

Hanley Engineering William L. Hanley - Surveyor in charge 2043 Main Street P. O. Box 701 Baker, Oregon 97814 Phone 523-3803

I, William L. Hanley, a registered surveyor in the State of Oregon, hereby certify that this plat and the notes contained hereon, or attached, are a correct representation of a survey performed by me, or under my direct supervision, during October and November, 1979, in full conformance with the Statutes of the State of Oregon

REGISTERED PROFESSIONAL LAND SURVEYOR

William, L. Hanly

OREGON
JULY 14, 1978
WILLIAM L HANLEY
1639