Comments on Corner Monuments

All section corners and the West quarter corner of Section 30 have been re-established with brass cap monuments by the BLM.

The South quarter corner was re-established with a brass cap monument from existing original accessory evidence.

The North and East quarter corners have been destroyed by dredging operations and were re-established by single proportionate measure.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
JULY 14, 1978
WILEIAM L. HANLEY

William L. Hanley ORLS 1639

WLH: dld

Page 2

FILED JULY 11, 1979
BAKER COUNTY SURVEYOR
SURVEY NO. 9-37-27