and the state of the state of the state of BASIS OF BEARING O.S.H.D. Map Number 7B-34-15 (Tangent between P.T. 1905 + 25.96 and P.S. 1913 + 65.67 being North 70°56′50″East Dayhoff REFERENCE MATERIAL N 84°34'21" Survey Number 9-45-20 880.00 Survey Number 9-45-22 O.S.H.D. Map No. 7B-34-15 Original G.L.O. notes Deed Number 79 03 106 Land contract No. 80 52 089 LEGEND Found 5/8" pin set by Oregon State Highway (unless otherwise noted) Found marked stone, replaced with 11/2"x 36" iron pipe with brass cap (see remonumentation sheets filed separately) Set 5/8"x 30" iron pin with plastic cap marked BGA SURVEY MARKER Dayhoff Existing fenceline NARRATIVE entire section as would be required by Mr. Porter's deed (to place his North line parallel to and 330 feet South of the Northeast 1/4 of the Northeast 1/4), I located the point which is 330 feet South of the Northeast corner of the Southeast 1/4 of the Northeast 1/4 and ran the line parallel with the South line of Porter. We This survey was ordered by Douglas Porter. I found a well marked stone of call size in a rock jack and placed a brass cap at the rock jack for the Northeast corner of Section 18. The Southeast corner of Section 18 has been previously monumented with a brass cap. I did not locate the East I/4 corner of with the South line of Porter. We discussed this with Mrs. Dayhoff, who (1892 + 24.10 Section 18, as it falls in the State Highway road prism. I therefore proportion the 1/4 corner into position. owns all around Porter and who was the The East line of Porter is based on the grantor and she agreed to this. Mrs. Dayhoff indicated that the existing fence line on Porter's North was the intended deed line, and the fence fits very well. line drive between the section corners. I found a well marked stone of called size at the West 1/4 corner of Section 18. Original notes call for a granite It is our intention to file a corrective deed as per our survey to clear up the possible controversy. I find no easement for access for the Porter land. The existing road at the Southwest corner of Mr. Porter's land does not cross his stone. This stone however, is a basalt stone with a well marked 1/4 on its West face. This stone was located within a half foot of the fence corner Long chord= 1885+26.66 accepted for the 1/4 corner on survey number 9-45-20, as filed in the office S 53°54'35"W property for several hundred feet after it leaves State of Oregon property. I have set a reference pin at the 89.24 feet of the Baker County Surveyor. I therefore NOTE: accepted the stone as the 1/4 corner. intersection of the spiral long chord and the South line of the Northeast 1/4, Set pin on the intersection of the long chord of the spiral and I also noted that the distance from 1/4 corner to 1/4 corner was some 250 feet short of a mile. I base the South line on the line drive between the and have called to the spiral curve the South line of the Northeast 1/4 of Section 18. intersect for convenience. proportioned 1/4 corner and the found 1/4 corner. Rather than break the - 167.44 (706.71 pin to pin) 712.56 S 84° 34' 21" W FILED April 28, 1982 BAKER COUNTY SURVEYOR 1882 + 26,66 5035.42 SURVEY NO. 9-45-30 State of Oregon BAGETT - GRIFFITH & ASSOCIATES REGISTERED La Grande, Oregon € Spiral Data PROFESSIONAL Map of Survey T9 S LAND SURVEYOR L= 300' A portion of the Southeast 1/4 of the S= 6°00' a= 1 1/3 Northeast 1/4 of Section 18, Township Gregory T. Blockman Highway 9 South, Range 45 East, W.M. OREGON BAKER COUNTY, OREGON Found brass cap GREGORY T. BLACKMAN 19 20 SURVEYED FOR Doug Porter - 991 _-4/82 SURVEYED BY ⊹∕⊹GTB 4/82 Scale: 1"=100' Drawn by: RGR PORTLAND PRECISION INSTRUMENT