MATCH LINE
SHEET 3

MATCH LINE
SHEET 3

Found Bureau of Land Management brass cap monument and accessories as set in 1970, from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1970, from original evidence.

S7 S8
S18 S17

(N88°23'W)
{N88°30'00"W}
N88°32'08"W
2605.08
{2604.00}
(2621.85)

J-7

(N88°23'W)
N88°35'34"W
2610.88
(2621.85)

J-9

S8 S9
S17 S16

(N88°50'W)
N88°50'36"W
2620.15
(2630.10)

L-11

(N88°50'W)
N89°09'58"W
1311.84
(1315.05)

L-12

(N88°50'W)
N89°09'58"W
1311.84
(1315.05)

S9 S10
S16 S15

(NORTH)
{N00°03'00"W}
N00°03'25"W
2604.18
{2604.60}
(2640)

{N00°13'10"W}
N00°14'57"W
1305.55
{1305.70}

N 1/2 NE 1/4
78.40 ac.
N.F.S.L.

See NARRATIVE
(NORTH)
{N00°17'50"W}
N00°19'30"W
1307.50
{no dist. on plat}
(1320)

N 1/2 NW 1/4
78.68 ac.
N.F.S.L.

N00°18'09"W
1306.31

N 1/2 NE 1/4
78.94 ac.
N.F.S.L.

(NORTH)
<N00°14'15"W>
N00°14'58"W
1309.88
<1309.91>
(1320)

NW 1/4
156.13 ac.
PVT.

K-7

{N88°22'40"W}
N88°26'34"W
2612.78
{2612.40}

K-9

Found brass cap monument with no accessories as set by Leland Myers in 1976.

N88°56'38"W
2619.52

K-11

N89°05'41"W
2635.49

K-13

Found brass cap monument with no accessories as set by Leland Myers in 1976.

N00°13'54"W
1305.15

See NARRATIVE
(NORTH)
{N00°17'50"W}
{N00°18'10"W}
N00°18'24"W
1309.88
(1320)

S 1/2 NE 1/4
78.42 ac.
PVT.

S 1/2 NW 1/4
78.64 ac.
PVT.

N00°18'09"W
1306.31

S 1/2 NE 1/4
79.29 ac.
PVT.

(NORTH)
<N00°14'15"W>
N00°14'58"W
1309.88
<1309.91>
(1320)

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

L-5

{N88°21'10"W}
N88°23'50"W
2613.61
{2613.90}

L-7

{N88°21'10"W}
N88°22'18"W
2614.64
{2614.40}

L-9

Found brass cap monument and accessories as set by Leland Myers in 1976. See NARRATIVE.

N89°01'26"W
2619.34

L-11

N89°01'26"W
2647.31

L-13

Found aluminium cap monument and accessories as set by O.R.L.S. 1106 in 1986, from original evidence. See Baker County Map of Survey No. 11-39-20.

{N00°13'10"W}
N00°14'35"W
2631.42
{2630.70}

SE 1/4
157.68 ac.
PVT.

(NORTH)
N00°19'15"W
2621.84
(2640)

SW 1/4
157.94 ac.
PVT.

N00°18'09"W
2633.57

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

N-7

(N88°26'W)
N88°35'02"W
2617.91
(2630.10)

S17 S16
S20 S21

(N88°32'W)
N88°46'02"W
2618.79
(2632.08)

N-11

Found Bureau of Land Management brass cap monument and accessories as set in 1972, from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1970, from original evidence.

DECLINATION 20° EAST

BASIS OF BEARING DETERMINED BY SOLAR OBSERVATIONS

500 0 500 1000 1500

Scale: 1"= 500'

REGISTERED
PROFESSIONAL
LAND SURVEYOR

OREGON
JULY 12, 1968
DOUGLAS M. FERGUSON
848

FILED Jan 22, 1992
BAKER COUNTY SURVEYOR
SURVEY NO. 11-39-72