T 6 S R 39 E

one foot West of monument.

Monument mkd. thus: S 23 | S 24

- Corner common to Sections 22, 23, 26 and 27: GLO records R-17 state "set post for corner to Sections 22, 23, 26 and 27 in mound of earth...". Found 4-way fence intersection. Point not monumented this survey.
- Quarter corner common to Sections 23 and 26: GLO records state "set post for corner in mound of earth". Found fence R - 19corner, fence runs North, West and Southeasterly. Set 5/8inch x 30 inch rebar with plastic cap mkd. HANLEY ENGRG PLS 1206.
- Corner common to Sections 23, 24, 25 and 26: GLO records state "set post for corner to Sections 23, 24, 25 and 26 in R - 21mound of earth with charred stake..". Found charcoal remains one foot under surface in center of 3 stone mound (large stones) in ancient fenceline remains. Set 2½-inch brass cap on 1½-inch diam. iron pipe projecting 2 inches above ground with 36 inch diam. stone mound around the monument. Set fence post alongside.

T 6 S R 39 E S 23 | S 24 Monument mkd. thus: S 26 | S 25 CS 1989

- Quarter corner between Sections 24 and 25: GLO records R - 23state: "set post for corner in mound of earth...". Set a 5/8-inch x 30 inch rebar with plastic cap mkd. HANLEY ENGR PLS 1206 in North-South running fence line on line between Southeast and Southwest section corners.
- Corner common to Sections 19, 24, 25 and 30: GLO records state "set post corner to Sections 19, 30, 24 and 25, made mound of earth"... Found a 15 x 11 x 9 inches stone in R - 25rock jack mkd. with 6 grooves on each of two sides and 2 grooves on one other side. Accepted rock jack for corner position. Did not remonument.
- Quarter corner between Sections 26 and 27: GLO records T-17state "set post for corner in mound of earth...". Set  $2\frac{1}{2}$ -inch brass cap on  $1\frac{1}{4}$ -inch iron pipe, 30 inches long in 36 inch diam. mound, in North-South running fence line at proportionate distance between Northwest and Southwest section corners.

T 6 S R 39 E

Monument mkd. thus:

CS 1989