

Narrative
(continued)

Mr. Hanley set a monument on the center line of section 27 where it crosses the Southerly line of the Eagle Quartz lode. I found this monument to be in error. I discussed this with Mr. Hanley and he requested that I remove his monument. I set my monument at the true point of intersection and removed his.

I found one bearing tree to corner number 2 of Annex Placer claim, mineral survey number 6. This was used to establish the corner number 2 of said Annex claim, however corner number 2 was not monumented. This corner will fall in Pine Creek. I do make calls to corners in the immediate area to perpetuate this position.

I found no other problems on this survey which I feel are not explained on the maps or in the remonumentation sheets.

