CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W.B.Barr under GLO contract no. 358 dated June 14, 1880.

Surveyor General records state: Marked basalt rock $16 \times 10 \times 10$ " for corner to Secs 17, 18, 19 & 20. Raised mound of rocks as per instructions.

Corner REMONUMENTED by USDI-BLM in 1983 under Group No. 1169, Oregon... The cor of secs 17, 18, 19 & 20 monumented

No. 1169, Oregon... The cor of secs 17, 18, 19 & 20 monumented with a sawed off steel fence post 3' long firmly set 12" in the ground. A conversation with local landowner John Stansberry revealed that he set the fence post at the position of the original corner stone found by James H. Hambleton, Registered Land Surveyor No 645, in 1980. The subsequent owner of the adjoining land then constructed wire fences extending N and E from this point which is accepted as the best available evidence of the position of the original corner. At the corner point...Set an iron post 28" long 2½" diam 22" in ground with brass cap mkd. (as in diagram). Deposit the steel fence post alongside the iron post.

Description of corner evidence found:

Corner is located at corner of wire fences extending N & E.

Found: $3\frac{1}{2}$ " brass cap on $2\frac{1}{2}$ " iron pipe projecting 6" out of small surrounding rock mound alongside fence corner post from which the fences run N, E & W.

Description of monument and accessories I established to perpetuate the original location of this corner:

MAINTAINED corner monument by improving surrounding rock mound, installing a steel fence post with sign 54-9 attached and establishing the following reference monuments, there being no trees or bearing objects available within limits...

A 5/8" x 30" rebar in an existing fence line brs $N2^{10}_{2}W$, 27.3' dist with a 1^{1}_{2} " aluminum cap attached and marked as shown: A 5/8" x 30" rebar in an existing fence line brs S83 E, 24.4' dist with a 1^{1}_{2} " aluminum cap attached and marked as shown:

Each reference monument has fence post alongside with signs 54-3 and 54-9 attached.

Compass declination 20° East.

I hereby certify that the above described corner monument was properly maintained by me on March 31, 1987.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

2M 520

244

DIAGRAM

S 18

S 19

T 8 S R 45 E

1984

S 17

S

20

OREGON
JULY 14, 1978
WILLIAM L. HANLEY
1639

William

Office of County Surveyor	County of Baker
Oregon , I hereby certi	fy that the within instrument was filed in this office
for record on the day of	
(COUNTY OFFICIAL)	. by(DEPUTY)

Form R6-7100-57 (9/71)

☆ gPO-798-276

BAKER COUNTY SURVEYOR
SURVEY NO. 8/45/79