



BASIS OF BEARING  
SUR. NO. 8-46-29 AND 32

1/16 CORNER MONUMENT DESTROYED BY SEWER WORK. SUR. NO. 8-46-29 SHOWS RELATIONSHIP 1/16 LINE TO CENTERLINE GROVER LANE.

**NARRATIVE**

THIS SURVEY FOR MARYELLEN OLSON IS FOR THE PURPOSE OF MARKING ON THE GROUND THE EXTERIOR BOUNDARY AND DIVISION OF A 120 FT. PARCEL INTO 50 FT. AND 70 FT. LOTS. RECOVERY OF STREET MONUMENTS ALONG DAWSON STREET AND GROVER LANE. THE SUBJECT PARCEL LIES WITHIN A TRACT OF LAND SURVEYED IN 1981, COUNTY FILE 8-46-32. THE BEARINGS ON THAT SURVEY ARE HELD.

**LEGEND**

- FOUND MONUMENT AS NOTED
- SET 5/8" x 30" REBAR WITH PLASTIC CAP MKD "HANLEY ENGRG PLS 1206"
- ( ) RECORD PLAT DISTANCE
- ⊠ SPIKE IN STEEL CASE MON. BOX

**MAP OF SURVEY**

FOR  
MARYELLEN OLSON  
IN  
HALFWAY, OREGON  
SURVEYED AUGUST 2, 1995  
AND OCT. 25, 1996

FILED NOV 22 1996  
DAKER COUNTY SURVEYOR  
SURVEY NO. 8-46-70

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*James D. Hanley*  
OREGON  
SEPTEMBER 23, 1977  
JAMES D. HANLEY  
1206

RENEWS JUNE 30, 1997

ENGINEERING  
TY, OREGON