

NARRATIVE FOR INFORMATIONAL MAP OF SURVEY OF SECTION 29, T9S, R37E, WM
Page 3 of 3

As I worked on this project anew, I found an oversight on my part. In 1971, one of my first survey projects was dividing SE1/4NW1/4NW1/4 of Section 29 into two five acre parcels. The first time was using Jim Hanley's North quarter corner which we eventually learned was substantially incorrect. I reset my monuments after finding the original North quarter corner in 1979, then I set the project aside and unfortunately forgot about it while waiting for Jim to do his correcting surveys. And now with my restructuring of the East half of Section 29, these monuments again need to be adjusted. I am showing the adjusted monuments for this survey as a new recording on this map long past due. I believe this is the only project that dates that far back in this general vicinity.

I believe this map is the least that should be done to correct the surveys done since about 1971. We could tweak things forever, but I think these adjustment create the least impact to land owners. I have many more historical notes as to Section 29 surveys that I am willing to discuss with anyone should they determine more information is needed or if you feel I am not correct with my evaluation. I am embarrassed to have taken 30 years to finally address this problem on the public record, but I feel it is too important to ignore any longer.

REGISTERED
PROFESSIONAL
LAND SURVEYOR



OREGON
JULY 9, 1965
LELAND LEE MYERS
699

Renewal Date 1/1/09

Filed OCTOBER 31, 2008
Baker County Surveyor
Survey No. 9-37-293