



Meridian based on O.S.H.D. Map No. 7B-34-15; The tangent between PT 1905+25.96 and PS 1913+65.67 bears N. 70° 56' 50\"/>

**NARRATIVE:** Corners were found or re-established as noted and section subdivided by prescribed method, the initial point being the corner common to sections 17, 18, 19 and 20. A dated fence corner was accepted as the true corner and re-monumented with a 2½ inch brass cap on a 1 inch iron pipe.

- LEGEND:**
- Indicates found corner as noted
  - ⊙ Indicates corner not found - re-established by calculation.
  - ⊙ Indicates set 2½" brass cap on 1" I.P.
  - ( ) Indicates G.L.O. record.

**REFERENCE SURVEYS:** 9-45-20 - and O.S.H.D. Map No. 7B-34-15

**MAP OF SURVEY**

**THE SUBDIVISION OF SECTION 17, T. 9S., R. 45 E., W.M. AND THE S½ SW¼**

**REGISTERED PROFESSIONAL LAND SURVEYOR**

*William L. Hanley* surveyed March 7 and April 3 & 8, 1980  
for Bob Harlan and Earl Baker

Scale 1"=1000'

**OREGON**  
JULY 14, 1978  
**WILLIAM L. HANLEY**  
1639

**FILED** April 17, 1980  
**BAKER COUNTY SURVEYOR**  
SURVEY NO. 9-45-21