RECORD OF LAND CORNER MONUMENTATION

Description of corner evidence found and history:

I found surveys that used the section corner for the division of sections, but the corner had never been monumented. The corner position is in the center of Moody Lane and I did not find any evidence of any kind for the corner.

aldry låda.	THE WAY	1.色杂彩	18 1 E
DIAG	KAM		
• • • • • •	a C		多种的类
	Tas	R45E	
	S14	S13	
MAY A	314	313	
	and the state of	13.00 F 14.00 13.00 F 14.00	
	S23	S24	
	A. A	200	
W. B.	PLS		
	20	04	
	野技法		Or it is the
CAME SECTO		party Napolitics	4 (1) (1) (2) (2) (2) (3) (4) (4) (4) (4) (4) (4) (4) (4) (4) (4

Description of monument and accessories I established to perpetuate the original location of this corner:

I set a 30" long 1" galvanized pipe with a 2 ½" brass cap 36" in the ground so that the cap is 6" below the road surface in line with fences to the East and West and made ties to the following references:

The SW corner of a RR tie post bears NE, 30.25 feet;

The SE corner of a RR tie gate post bears NW, 31.9 feet;

The SW corner of concrete ditch weir bears SW, 28.4 feet;

and the NW corner of a RR tie post bears SE, 32.85 feet.

REGISTERED **PROFESSIONAL** LAND SURVEYOR

> الصائد **OREGON**

JULY 9, 1965

LELAND LEE MYERS

Renewal Date 1/1/2007

BAKER COUNTY SURVEYOR

RECEIVED FEBRUARY 14 7005

ACCEPTEDFESICUALY 14, 2005

SURVEY No. 9-45-78

CP DWG-No. /14

INDEX No. T9S R45E N-21