In 1974 the Bureau of Land Managment re-monumented this corner as follows:

The corner of sections 9,10,15, and 16, monumented with the original basalt stone, (record, sandstone) 14x10x8 ins., firmly set 10" in the ground, marked with 4 grooves on S face, and 3 grobves on E. face, form which the remains of the original bearing trees:

A Ponderosa Pine 15" dia. bears N30°E, 25 lks dist. with healed double blaze. A White Fir snag 20" dia. bears S55°E, 47 lks dist. with healed double blaze. A White Fir stump 24" dia. bears S10°W, 47 lks dist., no marks visible. A Larch 23" dia. bears N35°W. 41 lks dist. with scribe marks S9 bt visible on partially healed double blaze.

At the corner point.

Set an iron post, 28 ins. long $2\frac{1}{2}$ ins. dia., 16 ins in the ground, to solid rock, and in a mound of stone, $3\frac{1}{2}$ ft. base, to top, with brass cap marked..

> T11S R37E S9 | S10 S16 S15 1974

From which new bearing trees. A Ponderosa Pine still, till dia. bears S60°E, 32 lks dist., marked T11S R37E S15 BT. A " 14" dia. bears S41 $^{\rm O}$ W, 17 $^{\rm L}$ 2 1ks dist. marked T11S R37E S16 BT. Deposit corner stone alongside iron pipe.