

S. 89° 49' 10" E. 5,432.92

Corner not found, location in cultivated field. Was found by Oregon State Highway Dept. and shown on O.S.H.D. Drng. No. 38-22-25 of March, 1933 to be N. 78° 47' E., 2186.3 ft. from Hwy. P.I. 1083+83.1. This P.I. was located, this survey, and the hwy. tie used to calculate the original corner position.

Not Found

Found, Mound

N. 0° 22' 5" W. 5,344.11

Not Found

S. 89° 42' E. 2,691.73

17
5,427.16

S. 89° 42' E. 2,755.43

Found, Stone

N. 0° 14' 45" W. 2,683.27

N. 0° 09' 25" E. 2,638.56

Set Pipe 685.87

Set Pipe 685.87

S. 89° 53' 30" E. 2,743.48

Set Pipe

N. 0° 11' 56" W. 2,620.26

Found Ref. Mon. 30 ft. N. & Ref. Mon. 30 ft. W. of Sec. Cor. N. 89° 35' E. 2,667.20

B.L.M. Brass Cap Elevation Marker for 1/4 Sec. Cor.

687.88

Set Pipe 687.88

S. 89° 55' W.

Set Pipe 687.88

687.88

Set Pipe 687.88

Found, Mound

N. 0° 37' 30" W. 2,665.42

N. 0° 37' W. 1,364.56

S. 0° 20' 40" E. 1,370.62

SUN NO. 2

S. 0° 04' 30" E. 1,376.68

SUN NO. 3

S. 0° 11' 40" W. 1,382.79

Set Pipe 681.43

Set Pipe 681.44

N. 89° 34' 15" W. 2,725.74

Set Pipe 681.43

681.44

Set Pipe 681.44

N. 0° 27' 40" E. 2,771.85



T. 11 S., R. 43 E., W.M.

20
5,368.0

S. 89° 05' E. 5,368.0

2,700.15

Not Found, Set 3/8" Steel Pin

S. 0° 37' 30" E. 2,665.42 to SW Cor. Sec. 20 Iron Pipe

S. 0° 37' E. 2,722.08 to S 1/4 Cor. Sec. 20 Stone

S. 0° 27' 40" W. 2,771.85 to SE Cor. Sec. 20 Iron Pipe

MAP OF SUBDIVISION OF SECS. 17 & 20, T. 11 S., R. 43 E., W.M., BAKER CO. OREGON. OREGON PORTLAND CEMENT CO. CLAIMS Surveyed Dec. 1963 & Jan. 1964 Scale 1" = 400'

FILED Jan 28, 1964 BAKER COUNTY SURVEYOR SURVEY NO. 11-43-1

2808 James S. Hanley