CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None. Corner established with this survey.

D-25 1	
DIAGRAM	
T 12 S	
$\mathbf{S} 1$	
R 36 E	R 37 E
S 1	S 6
1987	
PLS	1106

Description of corner evidence found:

None.

There is a 1957 USFS location poster on a 30" douglas fir 20' NW of corner point.

Description of monument and accessories I established to perpetuate the original location of this corner:

At position established by survey...

Set $2\frac{1}{2}$ " aluminum pipe with $2\frac{1}{2}$ " aluminum cap 20" in the ground and surrounded with a mound of earth and stone. Cap marked as shown in corner diagram.

New bearing trees established: A 9" douglas fir brs N54 $\frac{1}{2}$ E, 39.4' dist mkd S1/16S6 BT. A 8" juniper brs S04 $^{\circ}$ W, 73.7' dist mkd S1/16S1 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached signs 54-3~&~54-9, painted face of blaze and 6" band of red around each BT. Set steel fence post South of corner and attached sign 54-9.

Compass declination 190 East.

I hereby certify that the above corner monument was properly established to U.S.F.S. standards by me on November 17, 1987.

REGISTERED PROFESSIONAL. LAND SURVEYOR Willi R. Wells OREGON

JULY 22, 1977 WILLIAM R. WELLS 1106

Office of County Surveyor	County of Baker	
State ofOr.eg.an , I hereby certify that the within instrument was filed in this office		
for record on the day of		
by		
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

FILED 1-21-88 BAKER COUNTY SURVEYOR SURVEY NO. 12-37-19 **☆** GPO--798-276