

used intersection of fence line and center of county road as sec. cor being  $N100^{\circ}08'44''E$  5295.35 feet from the SW cor of Sec. 10 T8S, R39E WM. The northerly line of sec. 10 bears  $N89^{\circ}23'59''E$  and lies along center of county road.

The original  $\frac{1}{4}$  cor has been destroyed due to farming, therefor reestablished  $\frac{1}{4}$  cor by proportional measurements.

(160.0 ch.)

$N100^{\circ}08'44''E$

10  
16

Sec. Cor. has been destroyed by farming, therefor reestablished by using recorded deed for tax lot 3600 T8S R39E.



Note: Meridian used this survey was determined by a solar bearing

SURVEY OF THE W<sup>2</sup> SW<sup>4</sup> SECTION 10  
T8S R39E WM  
Date 6-2-70 Scale 1"=200'

REGISTERED  
OREGON  
LAND SURVEYOR  
JAMES H. HAMBLETON  
JULY 10, 1963  
645

FILED March 28, 1973  
BAKER COUNTY SURVEYOR  
SURVEY NO. 8-39-9