

Found 2 1/2" brass cap on
1" I.P. 50' south of fc. cor.

1380.10' (21.0)

S. 89° 47' 18" W., 2694.49'

1314.39' (20)

269.28'

254.36'

Found 2 1/2" alum. cap
on 1" iron pipe.

S. 01° 49' 45" E., 243.94'

S. 32° 48' 40" E.,
76.33'

S. 19° 27' 10" E.,
86.58'

S. 39° 36' 25" E.,
13.09'

N. 0° 19' 46" W., 400.00'

S. 89° 47' 18" W., 607.66'

LEGEND:

- Indicates found subdivision corner as noted.
- Indicates found 1/2" rebar
- Indicates set 5/8" rebar

Basis of Bearings:
The Guide Meridian between
Range 39 and 40 east is
assumed to bear North.

MAP OF SURVEY

A PARCEL IN THE N 1/2 OF THE NW 1/4
SECTION 19, T.9S., R.40E., W.M.

Surveyed Dec. 16, 1976 Scale 1"=100'

For David Irwin

FILED Jan. 3, 1977

BAKER COUNTY SURVEYOR

SURVEY NO. 9-40-23

