

NARRATIVE

By traversing between the found Northeast corner, the East quarter corner and the South quarter corners of Sec. 16: Reestablished the Southeast section corner of Sec. 16 (also being the Northeast corner of Section 20) from the CITY SURVEY OF 1970 map data. Highway I-80 construction has obliterated the fence corner marking the original section corner location. Set a 5/8-inch x 30 inch rebar on the basis of the above section subdivisional data for the Northwest corner of the NE4NE4 of Section 21.

The found monuments of an unrecorded survey for Tom Rudolph do not conform to the section subdivisional data and their significance is not known. See Legend.

MAP OF SURVEY

A PARCEL IN THE NEWNEW OF SECTION 21

T. 9 S., R. 40 E., W.M.

For Myrtle Petty and Bill Rudolph

June 2, 3, and 9, 1981 Scale 1" = 50'

PROFESSION
LAND UR TOR
James D. Hanley
JAMES D. HALLEY
1206