



Meridian by City Survey of 1970 - Survey No. 9-40-25.

**LEGEND**

- Monument of record as noted.
- Set 5/8" x 30" rebar with yellow plastic cap marked HANLEY ENGR PLS 1206
- [ ] Record of Survey No. 9-40-25.
- ( ) Record of Survey No. 9-40-59.
- Existing fence line.

**SURVEY NARRATIVE**

This survey was performed at the request of Dick Sheehy, acting for Esther Bunch, Earl Allen, Don Everson and Cheryl Cornett for the purpose of redescribing certain parcels in the NE 1/4 NE 1/4 of Section 16, T. 9 S., R. 40 E., W.M., as they are now occupied. 5/8-inch x 30-inch rebar monuments were established to mark the proposed redescribed ownerships as shown herein. Section 16 was previously subdivided and record filed under survey dated January 17, 1971. Survey control from that previous survey was recovered and is the basis for this survey. U.S. Highway 1-84 right of way monuments were located and survey ties made during this survey and survey filed March 3, 1976. The right of way monument opposite Hwy. Sta. 2170 + 00 is obliterated and was not recovered this survey; it's position was reestablished from the above described survey.

FILED Dec. 27, 1983  
 BAKER COUNTY SURVEYOR  
 SURVEY NO. 9-40-207A

RECORD OF SURVEY PLAT  
 IN THE NE 1/4 NE 1/4 SECTION 16, T. 9 S., R. 40 E., W.M.  
 Surveyed Sept. 21 & Dec. 7, 1983 Scale 1"=100'  
 For Esther Bunch, Earl Allen,  
 Don Everson and Cheryl Cornett

REGISTERED PROFESSIONAL LAND SURVEYOR

James D. Hanley  
 OREGON  
 SEPTEMBER 23, 1977  
 JAMES D. HANLEY  
 1206