In 1974 the Bureau of Land Managment re-monumented this corner as follows.

The $\frac{1}{2}$ section corner of secs. 15 and 22, monumented with the original basalt stone, (record sandstone) 16x8x5 ins. loosly setin a mound of stone $2\frac{1}{2}$ ft. base 1 ft. high, marked $\frac{1}{2}$ on N face, from which the remains of the original bearing trees:

A Juniper 22" dia, bears $S85^{O}W$, 28 lks dist., with ax marks visible on partially healed double blaze.

At the corner point.

Set an iron post 28'' long $2\frac{1}{2}''$ dia. 6'' in the ground, to solid rock, supported in a mound of stone, 6 ft. base, to top with brass cap marked.

T11S R37E

12 S15

S22
1974

From which a new bearing tree.

A Juniper 8" dia. bears N27°W, 84 1ks dist., marked ½ S15 BT.

Deposit corner stone alongside iron post.