

R39E T11S
T12S

DOOLEY
T12S R39E

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

MAGNETIC DECLINATION 20' EAST



500 0 500 1000 1500
Scale: 1" = 500'

BASIS OF BEARING: SOLAR OBSERVATIONS

REGISTERED PROFESSIONAL LAND SURVEYOR
OREGON JULY 12, 1988
DOUGLAS M. FERGUSON
848

Found marked stone with 3 grooves on the East face and 5 grooves on the South face.

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Corner lost to "cat" trail and logging.

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Found 24' x 16' x 6" stone, no marks. Only stone larger than 4" dia. in this area.

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Found marked stone with 1 groove on the East face and 4 grooves on the South face.

Re-monumented by William L. Hanley, PLS 1639 from original evidence, in 1986

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

Found stone and unrecorded Bearing tree

Found Bureau of Land Management brass cap monument and accessories as set in 1972 from original evidence.

MATCH SHEET 2 SHEET 3

MATCH SHEET 2 SHEET 3