REPLAT NO. <u>P2009-006</u> BEING A REPLAT OF PARCELS 1 AND 3 OF PARTITION NO. P1990-009 AND A PORTION OF PARCEL 2 OF PARTITION NO. P1998-013 SITUATED IN THE NE1/4SW1/4 OF SECTION 17, T.9S., R.40E., W.M., CITY OF BAKER CITY, BAKER COUNTY, OREGON SURVEY COMPLETED FEBRUARY 3, 2009 NORTHERLY LINE OF PARCEL 2 P1998-013 1[N89*29'01"E 331.22] BAKER STREET NOT A PART SEE SURVEY NO. 9-40-552 BASIS OF BEARINGS RECORD LAND PARTITION PLAT NO. 1990-009 AS SHOWN N89°29'01"E 374.60 2[N89°29'01"E 374.68] FD DISTURBED SEE NOTE #4 ADDITION PARCEL 1 2.87 AC. SECOND .FD DISTURBED SEE NOTE #3 S STEWART S89°24'11"W 492.01 S89°24'11"W 186.61 305.40 3 [S89*24'11"W 186.62] OCK S89°24'11"W 305.44 BL PARCEL 3 PARCEL 2 1.23 AC. 1.48 AC. [N27*30'W] 5.61 N27°30'00"W FD DISTURBED INITIAL POINT SW COR. PARCEL 3 SEE NOTE #1 [N89'24'11"E 116.63] N89'24'11"E 116.63 [N89°24'11"E 305.44] € MON AT 14TH & BROADWAY N89°24'11"E 305.44 P1990-009 N89°24'11"E 73.37 ORIGINAL MONUMENT FD A 5/8" IRON PIN SET IN 73.3/ NOT FOUND N89°24'11"E 422.07 AN 8" DIAMETER CAST IRON FD DISTURBED CITY MONUMENT CASE 73.37 J SEE NOTE #2 €=N89°24'11"E [N89°24'11"E] FD A 5/8" IRON PIN WITH BROADWAY STREET N89°24'11"E 302.96 YELLOW PLASTIC CAP SET IN [N89*24'11"E 302.96] AN 8" DIAMETER CAST IRON CITY MONUMENT CASE

- FOUND A 1/2" IRON PIPE SET BELOW GROUND IN AN 8" DIAMETER CAST IRON CITY MONUMENT CASE UNLESS OTHERWISE SHOWN.
- FOUND 5/8" IRON PIN WITH ATTACHED YELLOW PLASTIC CAP MARKED "HANLEY ENGR. PLS 1206" FROM RECORD LAND PARTITION PLAT NO. 1990-009
- FOUND 5/8" IRON PIN WITH ATTACHED YELLOW PLASTIC CAP FROM RECORD SURVEY NO. 9-40-552
- FOUND 5/8" IRON PIN NO CAP FROM RECORD LAND PARTITION PLAT NO. 1990-009
- SET 5/8"X30" IRON PIN WITH ATTACHED YELLOW PLASTIC CAP MARKED "BENCHMARK SURVEYING"
- NO. 1990-009
- RECORD BEARING AND DISTANCE FROM PARTITION PLAT NO. 1998-013
- RECORD BEARING AND DISTANCE FROM SURVEY NO. 9-40-552

RECORD BEARING AND DISTANCE FROM PARTITION PLAT

UNION PACIFIC RAILROAD

NOTES:

- 1. PIN WAS FOUND DISTURBED POSSIBLY DUE TO LANDSCAPING ACTIVITY.
- PIN IS 0.22' SOUTH & 0.19' WEST OF RECORD POSITION
- 2. PIN WAS FOUND DISTURBED POSSIBLY DUE TO LANDSCAPING ACTIVITY. PIN IS 0.25' NORTH & 0.65' EAST OF RECORD POSITION
- 3. PIN WAS FOUND BENT POSSIBLY DUE TO CONSTRUCTION ACTIVITY. PIN IS 0.19' SOUTH & 0.07' EAST OF RECORD POSITION
- 4. PIN WAS FOUND DISTURBED BY FENCE BUILDING ACTIVITY. PIN IS 0.26' SOUTH & 0.30' WEST OF RECORD POSITION

CURVE TABLE

CURVE	RADIUS	DELTA	LENGTH	LONG CHORD BEARING—DIST.	
C1	1656.40	5.01,18"	145.17	S20°09'37"E 14	5.13
C2	316.20	8*28'24"	46.76	S13°24'46"E 4	6.72
C3	755.20	12.01,46"	158.56	S03*09'41"E 15	8.26
C4	292.20	12*52'40"	65.67	S09*17'32"W 6	5.54
C5	316.20	6°46'26"	<i>37.3</i> 8	S14°15'45"E 3	7.36
C6	316.20	1*41'58"	9.38	S10°01'33"E	9.38

REGISTERED **PROFESSIONAL** LAND SURVEYOR

OREGON NOVEMBER 30, 2007 JASON L. HATFIELD #69454

EXPIRES: 6/30/2009

BENCHMARK LAND SURVEYING 217 N. CANYON BLVD. JOHN DAY, OREGON 2101 MAIN STREET, STE 223 BAKER CITY, OREGON

541-575-1251 ~ 800-699-0516

REPLAT OF PARCELS 1 AND 3 OF PARTITION NO. P1990-009 AND A PORTION OF PARCEL 2 OF PARTITION NO. P1998-013 SITUATED IN THE NE1/4SW1/4 OF SECTION 17, T.9S., R.40E., W.M., CITY OF BAKER CITY, BAKER COUNTY, OREGON

SURVEYED FOR	ELLINGSON LUMBER C	OMPANY
SURVEYED BY	JLH & MCS	2/3/2009
Scale: 1"= 60'	Drawn by: JLH	SHEET 1 OF 2