


Index File No. Y-15 CORNER RECORD (SEARCH) Tract or Survey No. SEE COR. 27
 T 6 S R. 13 E R.D. UNION County Baker
 Merid. Willamette N.F. Wallows/Whitman State Oregon

CORNER DIAGRAM



DESCRIBE CORNER MONUMENT FOUND

None

DESCRIBE BEARING TREES OR OTHER OFFICIAL ACCESSORIES FOUND

Found cut up log of 15" B.T. This has been recently destroyed. No trace of corner. Entire immediate area had been trampled by crawler type vehicle. Other B.T. was not found in 1951.

PHOTO IDENTIFICATION DATA

Photo No. _____
 Filed At. _____
 Object Ident. _____
 Ident. By _____
 Signature _____

DESCRIBE CORNER LOCATION RELATIVE TO NEAR-BY FEATURES, ALSO HOW TO REACH CORNER

Alongside (North of) Eagle Creek Road.

PLANE COORDINATE POSITION DATA

State _____ Zone _____
 X _____
 Y _____
 Estab. By _____
 Agency _____

Signature _____ Title _____ Division _____ Headquarters _____ Date _____ 7100-52
 REV. 65 5

CORNER RECORD (PERPETUATION)

MONUMENT: DESCRIBE NEW MONUMENT SET, OR WORK DONE TO PRESERVE EXISTING MONUMENT

Set 1-inch galvanized iron pipe with 2-inch aluminum cap marked as shown.

ACCESSORIES: DESCRIBE NEW BT'S WITNESS OBJECTS ETC. ESTABLISHED, OR WORK DONE TO PRESERVE EXISTING EVIDENCE

Brass disc in concrete for reference monument established on south side of Eagle Creek Road, 263.60 ft. south and 554.67 ft. West of $\frac{1}{4}$ corner.


Work Done By J. D. Hanley Title Engineer Date 6-65 State Registration No. Oregon P.E. 2808

Certified Cor. Record Prepared? Yes No Filed At: _____ Date _____

REMARKS

This corner relocated from old traverse hub which had been set in 1951 from which the $\frac{1}{4}$ corner had been tied to at that time by the above.

SURVEY NO. 6-43-1



Index File No. _____ T. _____ R. _____ M. _____ Tract or Surv. No. _____