DIAGRAM

T7S RISE S32 | S33

8 518 4

TOS RIBE 1978

History of original corner establishment:

Corner originally established in 1881, by Eugene P. McCornack, under "General Land Office Contract" Ma. 398.

In 1978 the Bureau of Land Management Performed A Dependent Resurvey of A portion of the South Doundary of T.78., R.38E., under special instructions, dated March 13, 1978, approved March 28, 1978.

The Notes from that survey, as executed by

Date T. Bedell, cadastral surveyor, state:

(Abridged Notes) At proportionate distance; there is no remaining evidence the original corner. Set standard monument, mkd. (see DIAGRAM) from which:

fir, 17 ins. diam., bears N45E., 40 lks. dist., mkd. T75 R38E S33 BT # fir, 13 ins. diam., bears S85E., 22 lks. dist., mkd. T85 R38E S4 BT # fir, 10 ins. diam., bears S27W., 24 lks. dist., mkd. T85 R38E S5 BT

Description of corner evidence found: N17-1/2W., 19 1ks. dist., mkd. T75 R38E 532 BT

Found 2-1/2" iron pipe with 3" brass cap monument stamped as shown the DIAGRAM, set with 6" above the ground.

found all the trees as taken by the BLM in 1978, live in good condition, at record measurement, with scribing visible.

Description of monument and accessories I established to perpetuate the original location of this corner:

Maintained Corner monument by setting a steel post with warning sign 1 ft. north from corner.

Maintained accessories as follows: Mailed Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON **DECEMBER 2, 1983** J. DAVID BRINTON 2065

& Dril Bula

Corner maintained Sept. 15,1984 Witnessed by Douglas M. Ferguson, PLS 848

Office of	County of
State of / here	by certify that the within instrument was filed in this office
for record on the day of	, 19
	by
(COUNTY OFFICIAL)	(DEPUTY)

Form R6-7100-57 (9/71)

FILED 2-15-85

BAKER COUNTY SURVEYOR SURVEY NO. 7-38-62

රි - 3გ -

☆ GPO-788-276