## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner not previously established.

DIAGRAM T7S R43E S 10 . NW-SW 1/64 1984 'RLS 1928

Description of corner evidence found:

Corner not previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 30" long aluminum pipe with 3½" aluminum cap 6" above ground, marked as shown above.

Set steel post with signs 54-9 and 54-2 attached.

Scribed:

9" Spruce "NWSW 1/64 S10 BT" S40E 21.7' 9" Spruce "NWSW 1/64 S10 BT" N14W 18.7'

Nailed aluminum washers stamped "RLS 1928" above "BT" scribe on trees.

Painted blazes red and a 6" red band around trees.

Attached signs 54-3 & 54-9 to trees.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

1-20-86

1-20-86

OREGON
JULY 13, 1984
DUANE FEHRINGER
2118

n	ffi	CP	nf		护门		. 13	W.	1739		g (1 )	6	3		4,				3	>	Co	un	tv	of.	1			Ų.	171	M.	1	100	À,	4	(3)	172	1		+ 6.00	- ' 'y
0.00	* ·		a 3		115		7:36	6.00	100	100	## · · ·	1. 44.	1.7	:57	.52	ŷ.	100	3	4	1.11	11			11.17	500	100	(V. 5)	Α.,	1.5	100	. O		de,		- 4		15 6 %	40.00	. 6 %	1.1%
24.		san, a	. 17.0				160	3 20	e i i i	. 9		1	27.	33	1.	: 113		100	100	. 16		4. 3				*1.7	SU	un	er	it v	va	5 J	116	a	IN	tn	5	OTT	166	3
fo	r r	ec	ord	l o	n t	he.		<b>V</b>	. (	lay	01	۲.		<u>. ( ) (</u>			7.		( ) (	* )				19		4				10-8									Y V	
Ž.			) Y 18		177		7714									i di	3,5	Ş.	b	, ,									1.0	ľ.										\$
	8								1 3	2.00	IC I	1.0					: 12: 1:334	74					4		1			5	DÉ	PÜ	TY)	Ġ.	76			ď.	42			3

Form R6-7100-57 (9/71)

☆ GPO-798-276