CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None previously established.

H-	5
DIAGRAM	
T7S R	43E
S 1/	16
s 7	s 8
PLS]	206
198	37
The second secon	

☆ GPO---798-276

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a $2\frac{1}{2}$ " x 30" alum. pipe with a $2\frac{1}{2}$ " alum. cap 22" into the ground. Constructed a 36" dia. stone mound around the monument. The cap is marked as shown in the corner diagram.

From the corner point:

A 9" dia. Ponderosa Pine, bears N. 45° E., at 37.1 ft. dist., mkd.

A 12" dia. Ponderosa Pine, bears N. 36° W., at 75.7 ft. dist., mkd. S 1/16 S7 BT.

Set a steel fence post 4 ft. W. from the monument and attached a USFS 54-9 amd 54-2 signs. Painted the face of the blaze and a 6 in. band around the bearing trees red. I.D. washers were nailed between the scribed B and T of the new bearing trees. The washers are 3/4" in diameter and made of brass with PLS 1206 stamped on one side. Attached USFS 54-9 and 54-3 signs to bearing trees. Used $18\frac{1}{2}$ declination on a staff compass for readings to bearing trees. Used a steel tape to measure to a nail set in the side of the trees.

This corner was monumented to USFS specifications on July 27, 1987, witnessed by Tom Fisk and Andy Marlette.

office ofCountySu	rveyor
State ofUNday of for record on the day of	of
соинту оffic Form R6-7100-57 (9/71)	REGISTERED PROFESSIONAL LAND SULVEYOR
	James Mauly FILED 10/13/88