

# Corner Monumentation in Section 19, T. 7 S. R. 44 E. W.M. Baker County, Oregon

Forshey Cadastral Survey

① T7S  
R43E R44E  
S13 | S18  
S24 | S19  
1981  
RLS 1664

Fd : No evidence of BLM brass cap. Indication of hole where pipe had been.  
Ref: 34" PPBT. N 48°E - 127 lks (N 45 1/2°E - 127 lks)  
34" Fir B.T. S 56°W - 76 lks (S 56°W - 76 lks)  
12" PPBT. N 20°W - 65 lks (N 20°W - 65 lks)  
13" Fir B.T. S 23°E - 22 lks (S 23°E - 22 lks)  
9" Fir B.T. N 66°E - 15 lks (N 66°E - 15 lks)  
Comp. decl. 20° East  
Set: AP 25" in ground in mos.  
Ref: No new ones set.

② T7SR44E  
1/4 S18  
S19  
1974

Fd : 1974 BLM brass cap.  
Ref: 23" PPBT. S 80°W - 33 lks (S 80°W - 33 lks)  
24" PPBT. N 01°W - 42 lks (N 01°W - 42 lks)  
11" Fir B.T. S 44°W - 28 lks (S 44°W - 28 lks)  
Comp. decl. 20° East

③ T7S  
R43E R44E  
4  
S24 | S19  
1974

Fd : 1974 BLM brass cap.  
Ref: 30" Fir stump S 78°E - 77 lks (S 78°E - 77 lks)  
32" PP stump West - 5 lks (West - 5 lks)  
3" PPBT. N 74°E - 39 lks (N 74°E - 39 lks)  
11" PPBT. N 84°W - 46 lks (N 84°W - 46 lks)  
Comp. decl. 20° East

④ T7SR44E  
C 1/4 S19  
1982  
RLS 1664

Set: AP 26" in ground in mos.  
Ref: 8" WF.B.T. N 07°W - 19.3 ft.  
9" WF.B.T. N 64°E - 33.8 ft.  
Comp. decl. 20° East

⑤ T7SR44E  
1/4  
S19 | S20  
1981  
RLS 1664

Fd : 15"x12"x10" stone scribed 1/4". Stone was out of position.  
Ref: PP stump N 08°E - 41 lks (N 10°E - 56 lks)  
PP stump N 01°W - 22 lks (N 08°W - 22 lks)  
Set: AP 24" in ground in mos. Buried broken brown glass and original stone alongside new monument.  
Ref: 10" PPBT. N 09 1/2°W - 74.3 ft.  
9" PPBT. N 81°E - 31.8 ft.  
Comp. decl. 20° 20' East

⑥ T7S  
R43E R44E  
S24 | S19  
S25 | S30  
1974

Fd : 1974 BLM brass cap.  
Ref: 24" PP stump N 58 1/2°E - 66 lks (N 58 1/2°E - 66 lks)  
32" PPBT. S 32°E - 30 lks (S 32°E - 30 lks)  
24" PP stump N 25 1/2°W - 99 lks (N 25 1/2°W - 99 lks)  
8" PPBT. N 54°E - 28 lks (N 54°E - 28 lks)  
9" PPBT. S 63 1/2°E - 23 lks (S 63 1/2°E - 23 lks)  
10" PPBT. S 67 1/2°W - 82 lks (S 67 1/2°W - 82 lks)  
11" Fir B.T. N 03°W - 111 lks (N 03°W - 111 lks)  
Comp. decl. 20° East

⑦ T7SR44E  
1/4 S19  
RM  
1974

Fd : 25" PP, which is the original corner.  
Ref: Reference monument N 45°W - 15 lks, BLM brass cap, 1974  
28" PPBT. S 42°E - 33 lks (S 42°E - 29 lks)  
32" PPBT. N 66°W - 33 lks (N 66°W - 33 lks)  
8" PPBT. S 12°W - 137 lks (S 12°W - 137 lks)  
Comp. decl. 20° East

⑧ T7SR44E  
S19 | S20  
S30 | S29  
1974

Fd : 1974 BLM brass cap  
Ref: 25" Western Larch B.T. stump N 31°E - 10 lks (N 31°E - 10 lks)  
Root hole S 60°E - 20 lks (S 60°E - 20 lks)  
12" WF.B.T. N 12°E - 20 lks (N 12°E - 20 lks)  
13" WF.B.T. S 82°E - 82 lks (S 82°E - 82 lks)  
11" WF.B.T. S 06°W - 34 lks (S 06°W - 34 lks)  
8" WF.B.T. N 83°W - 23 lks (N 83°W - 23 lks)  
Comp. decl. 20° East

⑨ T7SR44E  
S19  
MS 126  
EMW-1  
1982  
RLS 1664

Fd : Mound of stone with 4"x4" wood post. Not original.  
Set: AP 24" in ground in mos. Buried broken clear glass alongside monument.  
Ref: 7" PPBT. N 31°E - 34.3 ft.  
6" PPBT. S 44°W - 33.9 ft.  
Comp. Decl. 20° East

⑩ T7SR44E  
S19  
MS 126  
EMW-2  
1982  
RLS 1664

Fd : Remains of two old wooden 4"x4" posts in mos.  
Set: AP 22" in ground in mos.  
Ref: 8" DF.B.T. North - 20.6 ft.  
10" DF.B.T. S 38°E - 25.4 ft.  
Comp. decl. 20° East

⑪ T7SR44E  
S30  
MS 126  
EMW-4  
1982  
RLS 1664

Fd : Old 4"x4" scribed post in mos.  
Set: AP 24" in ground in mos.  
Ref: 8" PPBT. N 54 1/2°E - 37.7 ft.  
9" PPBT. S 68°W - 16.9 ft.  
Comp. decl. 20° East

⑫ T7SR44E  
S19  
MS 126  
EMW-3  
1982  
RLS 1664

Fd : Remains of 4"x4" scribed post in mos.  
Set: AP 14" in ground in mos.  
Ref: 12" PPBT. S 64°E - 66.4 ft.  
8" PPBT. N 33°W - 21.3 ft.  
Comp. decl. 20° East

⑬ T7SR44E  
C-W 1/4 S19  
1982  
RLS 1664

Set: AP 25" in ground in mos.  
Ref: 10" Tamarack B.T. N 47°W - 42.5 ft.  
10" PPBT. N 84 1/2°E - 28.7 ft.  
Comp. decl. 20° East

⑭ T7SR44E  
S19  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 10" PPBT. N 54°W - 34.4 ft.  
9" PPBT. N 82°E - 34.4 ft.  
Comp. decl. 20° East

⑮ T7SR44E  
S19  
#2  
1982  
RLS 1664

Set: AP 24" in ground.  
Ref: 7" PPBT. N 29°W - 42.4 ft.  
9" PPBT. S 81°W - 1.5 ft.  
Comp. decl. 20° East

⑯ T7SR44E  
S19  
1982  
RLS 1664

Set: AP 6" below road surface.  
Ref: 11" PPBT. N 44°W - 111.0 ft.  
6" PPBT. N 02°E - 80.1 ft.  
Comp. decl. 20° East

⑰ T7SR44E  
C-S NW 1/4 S19  
1982  
RLS 1664

Set: AP 24" in ground in mos.  
Ref: 17" PPBT. S 55°W - 14.9 ft.  
11" PPBT. S 71°E - 73.8 ft.  
Comp. decl. 20° East

⑱ T7SR44E  
S19  
1982  
RLS 1664

Set: AP 6" below road surface.  
Ref: 9" PPBT. N 03°W - 65.1 ft.  
7" PPBT. N 26°E - 54.3 ft.  
Comp. decl. 20° East

⑲ T7SR44E  
S19  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 13" PPBT. S 63 1/2°W - 34.0 ft.  
13" Tamarack B.T. S 13°E - 48.3 ft.  
Comp. decl. 20° East

⑳ T7SR44E  
C-N-SE  
NW 1/2 S6-S19  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 7" PPBT. S 64 1/2°W - 51.7 ft.  
9" Tamarack B.T. S 50°E - 41.7 ft.  
Comp. decl. 20° East

㉑ T7SR44E  
S19  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 9" PPBT. N 40°W - 58.3 ft.  
9" PPBT. N 76 1/2°E - 52.7 ft.  
Comp. decl. 20° East

㉒ T7SR44E  
S19  
#3  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 15" PPBT. S 43°W - 70.0 ft.  
11" PPBT. S 77°E - 12.0 ft.  
Comp. decl. 20° East

㉓ T7SR44E  
S19  
#4  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 11" PPBT. S 34°W - 55.7 ft.  
9" PPBT. S 06°E - 29.4 ft.  
Comp. decl. 20° East

㉔ T7SR44E  
CN 1/6 S19  
1982  
RLS 1664

Set: AP 26" in ground.  
Ref: 7" PPBT. N 32°W - 33.8 ft.  
8" PPBT. S 33°W - 35.3 ft.  
Comp. decl. 20° East

㉕ T7SR44E  
S19  
#5  
1982  
RLS 1664

Set: AP 26" in ground in mos.  
Ref: 7" PPBT. N 84 1/2°E - 28.3 ft.  
8" PPBT. N 18°E - 69.1 ft.  
Comp. decl. 20° East

㉖ T7SR44E  
NW 1/6 S19  
1982  
RLS 1664

Set: AP 26" in ground in mos.  
Ref: 11" PPBT. N 49 1/2°W - 71.1 ft.  
13" PPBT. S 83°W - 62.3 ft.  
Comp. decl. 20° East

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Carl E. Sundet*  
OREGON  
JULY 14, 1978  
CARL E. SUNDET  
1664

Surveyed for: US Forest Service  
Contract No. 53-04M3-1-2667N  
Surveyed by: SUNDET AND ASSOCIATES  
P.O. Box 1228  
Lakeview, Oregon  
Ph. No. 947-3293

Date: 1981-82

Drawing No. 203C Sheet 3 of 3 Field Books 1 and 4

FILED Oct 19, 1982

BAKER COUNTY SURVEYOR  
SURVEY NO. 7-44-3B