## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not set.

Index File Number L-DIAGRAM

T7S R44E S17

Description of corner evidence found:

None.

## Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" aluminum pipe and cap

T7S R44E 

OR PLS 1051 Set pipe 22" in the ground and mound of stone around to cap.

From which by magnetic declination of N20°E: 1985
A 20" Fir, bears N33°E, 57.3 ft. scribed Cl/4 Sl7 BT. A 15"
Fir bears S54°E, 32.7 ft. scribed Cl/4 Sl7 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on the bearing trees. Placed 54-9 on a steel fence post 5! south of the corner.

> I hereby certify that the above corner monument was established as herein described.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1 0 5 1

Witnesses: Van K. Barbour Daniel J. McMillan

August 24, 1985.

O	ffice	of		Ċ	oùi	nts	z S	ur	VΕ	νC	'n	.S	a Y			c	้อน	ntv	O		E	al:	(e)	ĵ.		2 × 7	1	50.			i de		
4.	ate	12. 1	100	G 5 5 7	Sig-2011	11 T	1000		. 12	200	-1.30	45.1	26.50	20		100	316			1.30	4	21:	S - 6	3.74	8 V/	31.43	A.C	ੂੰ d i	ា n ប	his	off	ice	•
4.	r re	1987 200		200	A. 77.7		3.3	100		15 5 5		3,000		10.0	100	a Austra		5 6 5	200	9.77.9					N.			1.3	ye			P.S.	4
		513				ring Japan		A.			479. (3-138			3.V	bν						3.4						y ( je) Sesar	d'in	7				
				<b>(C</b>	:ou	NTY	OF	FIC	ΑL	)			giri.	8¥.7		7		w Kil		,			(D	EPU	JΤΥ	) 3				A 13.			

Form R6-7100-57 (9/71)

MED 11-7-85 PAKER COUNTY SURVEYOR **S**URVEY NO. 7-44-101 ☆ GPO-798-276