

CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File Number T-15

**History of original corner establishment:**

Not Set.

**DIAGRAM**

T7S R44E  
C1/4 + S27

**Description of corner evidence found:**

None Found.

**Description of monument and accessories established to perpetuate the original location of this corner:**

At surveyed point set 2 1/2" X 30" aluminum pipe and cap marked;  
Set pipe 24" in the ground and mound of stone around to cap.  
No trees for several hundred feet.  
Built mound of stone 5' base and 3' high, 5' west of the corner.  
Placed 54-9 on a steel fence post 5' north of the corner.

T7S R44E  
C1/4 + S27  
OR PLS 1051  
1984

I hereby certify that the above corner monument was established as herein described.

Witnesses: Michael E. Marks  
Robert W. Wilson

October 19, 1984,

REGISTERED  
PROFESSIONAL  
LAND SURVEYOR

*Barry B. Barbour*

OREGON  
OCT. 17, 1975  
BARRY B. BARBOUR  
1051

Office of.....County Surveyor..... County of.....Baker.....  
State of.....Oregon..... I hereby certify that the within instrument was filed in this office  
for record on the..... day of....., 19<sup>85</sup>  
..... by .....  
(COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

☆ GPO—798-276

FILED 11-7-85  
BAKER COUNTY SURVEYOR  
SURVEY NO. 7-44-130