## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not Set.

Index File Number X-19

DIAGRAM

T7S R44E

C1/4 S35

Description of corner evidence found:

None Found.

Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and brass cap marked:

Set pipe 24" in the ground and mound of stone around

T7S R44E

C1/4 - S35

OR PLS 1051

From which by magnetic declination of N20°E:
An 8" Pine bears S40°E, 16.0 ft. scribed C1/4 S35 BT. A 10" Fir bears N80°W, 18.2 ft. scribed C1/4 S35 BT. Painted blazes red and 6" red band around. Placed 54-3s, 54-9s and brass washers stamped PLS 1051 on the bearing trees. Placed 54-9 on a steel fence post 5' south of the corner.

I hereby certify that the above corner monument was established as herein described.

Witnesses: Michael E. Marks Robert W. Wilson

September 17, 1984.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Sarely B. Sarely
OREGON
OCT. 17, 1975
BARRY B. BARBOUR
1 0 5 1

Offina of	County Surveyor	County of	Baker	 
	Oregon , i hereby			
	n the day of			,
-	******************************			 
	(COUNTY OFFICIAL)			

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

FILED 11-7-85

BAKER COUNTY SURVEYOR
SURVEY NO. 7-44-168