## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Ні	story	of	origin	al come	establi	shment:
----	-------	----	--------	---------	---------	---------

Not Set.

Index File Number X-23

DIAGRAM

T7S R44E C1/4 - S36

## Description of corner evidence found:

None Found.

## Description of monument and accessories I established to perpetuate the original location of this corner:

At surveyed point set 2 1/2" X 30" galvanized pipe and C1/4 + S36 brass cap marked:

OR PLS 105

Set pipe 8" in the ground to bedrock and mound of stone around to cap.

mound of stone OR PLS 1051 1983 °E:

T7S R44E

From which by magnetic declination of N20°E:
A 14" Pine bears N65°E, 11.5 ft. scribed C1/4 S36 BT. A 12" Pine bears S67°W, 39.7 ft. scribed C1/4 S36 BT. Painted blazes red and 6" red band around. Placed 54-2 and 54-9 on a steel fence post 5' north and placed 54-2 on a steel fence post 5' south of the corner.

REGISTERED PROFESSIONAL LAND SURVEYOR

Savey B. Barebour

OREGON

OCT. 17, 1975

BARRY B. BARBOUR

1 0 5 1

I hereby certify that the above corner monument was established as herein described.

Witnesses: Larry D. Shirley Troy A. Slobig

November 4, 1983.

	County Sur	TO POST		County	of Ba	ker			
Office of	Oregon	.,/hereby	certify th	at the w	ithin ins	trument wa	s filed	in this o	ffice
for recor	d on the day	of			<b>19</b> 0.5.		1.		
	(COUNTY OFFI	CIAL)	by			(DEPUT)	······································	••••••	*****

Form R6-7100-57 (9/71)

FILED 11-7-85

BAKER COUNTY SURVEYOR

SURVEY NO. 7-44-171

☆ GPO---798-276