CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by W. B. Barr under GLO contract no. 443 dated May 29, 1882.

Surveyor General records state:

Set granite boulder $12 \times 10 \times 10$, 8 inches in ground for corner to Sec 25, 26, 35, 36 marked with 1 notch on East and 1 notch on the South edges from which:

R 45 E
S 25
S 36

A pine 5 in. diam bears N 57° E, 46 lks dist marked T 7 S R 45 E S 25 BT A pine 48 in. diam bears N 89° W, 302 lks dist marked T 7 S R 45 E S 26 BT A pine 40 in. diam bears S 87° W, 300 lks dist marked T 7 S R 45 E S 35 BT A pine 46 in. diam bears S 21° E, 10 lks dist marked T 7 S R 45 E S 36 BT

Description of corner evidence found:

Original corner monument not found.

Corner monument re-established at extended intersection of ancient fences running west and north. This position identified by Mr. Ladd Steele, landowner, as being his recollection of original corner location on Nov. 19, 1974, to Bill Hanley and Brad Gordon.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 1 inch iron pipe 31 inches long and 5 inches below road surface.

Brass cap marked thus:

T 7 S R 45 E

S	26	SS 25
S	35	S 36
•	CS :	1981

I hereby certify that the above described corner monument was properly established on Feb. 20, 1980, under my supervision and witnessed by Brad Gordon, Tom Fisk, and Jim DeMastus. PROFESSIONAL

A Charles

LAND SURYEYOR OREGON SEPTEMBER 23, 1977 JAMES D. HANLEY 1206

REGISTERED

Office of		Coun	ty of			
State of	hereby certi	fy that the	within	instrument	was filed	l in this office
for record on the day of			. 19	••		
(COUNTY OFFICIAL		77 * 14 14	198	(DEP		

Form R6-7100-57 (9/71)

FILED March 18,1981 BAKER COUNTY SURVEYOR SURVEY NO. 7-45-67

☆ GPO---798-276