CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not previously established.

5 25	1.0	10.7	1.7	100
		• ^	** *	985
		71.7 -	w e	ากก
- 13		4G	"	1177

T7S R45E

S34 · C 1/4

1984

RLS 1928

Description of corner evidence found:

Not previously established.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 30" long aluminum pipe with a $3\frac{1}{4}$ " aluminum cap, marked as shown above, 7" above ground. Steel post with signs 54-9 & 54-2 next to cap.

Scribed:

lo" fir S.04°W. 42.0' "C 1/4 S34 BT" 11" fir N.73°W. 34.2' "C 1/4 S34 BT"

Attached signs 54-3 & 54-9 and nailed aluminum washers stamped "RLS 1928" by "BT" scribe on both trees. Painted blazes red and a 6" red band around each tree.

PROFESSIONAL
PROFESSIONAL
PROFESSIONAL
AND SURVEYOR
LAND SURVEYOR
OREGON
JULY 13, 1984
DUANE 2118
DUANE 2118

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

FILED May 9, 1986

BAKER COUNTY SURVEYOR

SURVEY NO 7-45-142