## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established this survey.

Diagram

T 7 S R 46 E

 $C \frac{1}{4} S 22$ 

Description of corner evidence found:

None

Description of manument and accessories I established to perpetuate the original location of this corner:

Set a 2½ inch brass cap on a 2 inch iron pipe 31 ins long 28 ins in the ground with a surrounding rock mound and a 6 ft steel fence post 5 ft North with a sign 54-9 attached.

Brass cap marked thus: T 7 S R 46 E

C ¼ S 22

1979 ORLS 1639

New bearing trees:

A pine O6 ins diam bears S O7° E, 41.2 ft dist mkd C 1/4 S 22 BT A pine 12 ins diam bears N 68° W, 15.7 ft dist mkd C 1/4 S 22 BT

Each BT has a sign 54-3 attached below a band of red paint and has a brass washer marked LS 1639 nailed flush with BT blaze.

I hereby certify that the above monument was properly established this survey as herein described on August 3, 1979 witnessed by Tracy Labaree and Jim DeMastus.

REGISTERED
PROFESSIONAL
LAND SURVEYOR

William & Hearle

OREGON
JULY 14, 1978
WILLIAM L. HANLEY

Office of		County	y of	
State of / hereb	y certify the	et the w	within instrument was filed in this offic	8
for record on the day of	,		. 19	
	by		***************************************	
(COUNTY OFFICIAL)	······································		(DEPUTY)	
	Λ	.att.		

Form R6-7100-5/ (9/71)

FILED Aug 9, 1979

BAKER COUNTY SURVEYOR

SURVEY NO. 7-46-32

प्रे GPO---796-278