


CERTIFIED RECORD OF LAND CORNER MONUMENTATION

Index File No, P-11

History of original corner establishment:

NOT SET



Description of corner evidence found:

NONE

Description of monument and accessories established to perpetuate the original location of this corner:

At the center of the surveyed point, set 2 1/2" X 30" galvanized pipe and brass cap marked: Set pipe 22" in the ground and mound of stone around to cap.

No trees within limits.

Placed 54-9 on a steel fence post 5' E. of the corner, and raised a mound of stone 3 ft. base, 3 ft. high, 5 ft. west of the corner

T7S R47E
C1/4 + S21
OR PLS 1051
1981

I hereby certify that the above corner monument was established as herein described.

Witnesses: David Cummins
Daniel Rowland
Douglas Moser

February 20, 1981

REGISTERED
PROFESSIONAL
LAND SURVEYOR

Barry B. Barbour
OREGON
OCT. 17, 1973
BARRY B. BARBOUR
1051

Office of... County Surveyor..... County of... Baker

State of....., I hereby certify that the within instrument was filed in this office for record on the..... day of....., 1981.

..... by *Thomas J. [Signature]*.....
(COUNTY OFFICIAL) (DEPUTY)

FILED Feb 27, 1981
BAKER COUNTY SURVEYOR
SURVEY NO. 7-47-35