## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Not Set

Description of corner evidence found:

None

Description of monument and accessories I established to perpetuate the original location of this corner:

At the center of surveyed point, set 2  $1/2" \times 30"$  galvanized pipe and brass cap marked: Set pipe 18" in the ground and mound of stone around to cap.

No trees. Built mound of stone 5' west of the corner. Placed 54-2 and 54-9 on a steel fence post 5' east and placed 54-2 on a steel fence post 5' north of the corner.

T7S R47E Sl9

E ------ 1/16

S30 OR PLS 1051 1981

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON OCT. 17. 1375 BARRY B. BARBOUR 1 0 5 1 I hereby certify that the above corner monument was established as herein described.

Witnesses: Douglas Moser

April 22, 1981

Office of County	Baker
State of Oregon I hereby certify that the within instrument was filed in this office	
for record on the day of	
by thomas it totaling	
(COUNTY OFFICIAL)	(DEPUTÝ)

Form R6-7100-57 (9/71)

‡r GPO--798-276