## CERTIFIED RECORD OF LAND CORNER MONUMENTATION


## History of original corner establishment:

Corner originally established by John Hagel under Mineral Survey No. 428 and surveyed under instructions dated July 10,1901.

Original notes state:

Set a pine post 4 ins.square,  $4\frac{1}{2}$  ft.long,18 ins. in the ground, with a mound of rocks around it, scribed Lux.Q.Cl.,N.Cen.-428.

A spruce tree 8 ins.diam., blazed and scribed Lux.N. Cen.-428-B.T. bears N.67 $^{\circ}$ 05'E, 39.7 ft.



North Center Luxemburg

## Description of corner evidence found:

Found rotted remains of post at ground level in mound of stone, from which...

A 14" spruce brs  $N68^{O}E$ , 39.2' with healed blaze.(Original BT)

## Description of monument and accessories I established to perpetuate the original location of this corner:

At position of found post remains...

Set  $2\frac{1}{2}$ " x 30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap 26" in ground and surrounded with a mound of earth and stone. Cap marked as shown in corner diagram.

New bearing trees established: A 10" lodgepole pine brs  $S70\frac{1}{2}^{\circ}E$ , 27.3' scribed NC-L-428 BT. A 8" lodgepole pine brs  $S03\frac{1}{2}^{\circ}E$ , 29.6' scribed NC-L-428 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 & 54-9 to each BT & painted face of blaze & 6" red band around each BT. Set steel fence post on National Forest Boundary SE of corner with sign 54-2 & 54-9 attached.

Compass declination 180 East.

I hereby certify that the above corner was properly remonumented by me to U.S.F.S. standards on September 11, 1992.

PROF		MAL
Will	. R.	Wells
JUL	REGO Y 22, 19 A/A R. N 1106	)/ Z

Office of County Surveyor	County of Baker		
State ofOregon I hereby certify that the within instrument was filed in this office			
for record on the day of , 19			
by			
(COUNTY OFFICIAL)	(DEPUTY)		

Form R6-7100-57 (9/71)

☆GPO: 1989-692-049

FILED_	3-24	-93
BAKER	COUNTY	SURVEYOR
SURVEY	NO8:	36-79