CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

Corner established by Lincoln E. Wilkes under instructions dated Sept. 24,1923 and included in Group No. 107.

Surveyor General records state:

...set an iron post, 3 ft. long, 1 in. dia., 27 ins. in the ground, for 1 sec. cor. of sec. 24 only, with brass cap marked as shown in corner diagram from which:

DIAGRAM

\$ 24

P-25

T 8 S R 36 E

A spruce, 9 ins. dia., bears S. 23 W., 22 lks. dist., marked \$ 3 24 BT. A spruce, 6 ins. dia., bears N. 79 W., 31 lks. dist., marked \$ 5 24 BT.

Description of corner evidence found:

Ambrass cap on an iron pipe marked as shown in corner diagram.

A 13" diam. spruce enag bears S 2320 W., 22 lks. dist. with healed blaze.

A Spruce 18" diam. bears N 79° W., 31 lks. dist. with healed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

Improved surrounding rock mound around corner monument and set a 6 foot steel fence post alongside with a sign 54-9 attached.

New bearing tree:

A spruce 13 inches diam bears 8.56° W., 24.5 ft. dist. marked $\frac{1}{2}$ S 24 BT and has a brass washer marked PLS 1639 nailed flush with BT blaze.

To each bearing tree attached a sign 54-3 above BT blaze and below a 6 inch band of red paint and a blaze tree attached to opposite side of tree from BT blaze.

I hereby certify that the above corner monument was properly maintained to U.S.F.S. standards under my supervision on Oct. 4, 1984, and witnessed by Jim DeMastus and Daryl Schuchardt.

PROFESSIONAL LAND SURVEYOR

William J. Hanley

OREGON

JULY 14, 1978

WILLIAM L. HANLEY

1639

Office of	County	Surveyor	County of	Baker
State of	Oregon		ify that the within	instrument was filed in this office
			. bv	
	(COUNTY ((DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE + 1983 -793-276

FILED_	6-11	-85
BAKER	COUNTY	SÜRVEYOR
SURVEY	′ NO	8-36-2