J - 21

History of original corner establishment:

 $A_{2}(t)$ 

This corner was originally established by William R. Gradon, U.S. Deputy Surveyor, under his Contract No. 409, dated March 28, 1882, during May and June, 1882. The original notes state that at the corner a 18"by12" by 4" marked basalt stone was set 12" in the ground from which:

DIAGRAM T9S R36E S11 | S12 S14 | S13

A.20" tamarack bears N65°E-67 lks, scribed T9S R36E S12 BT.

A 36" pine bears S35°E-521ks, scribed T9S R36E S13 BT.
A 30" pine bears S65°W-78 lks, scribed T9S R36E S14 BT.
A 18" tamarack bears N65°W-70 lks, scribed T9S R36E S11 BT.

Description of corner evidence found:

A 15"by12"by4" basalt stone lying loose on the ground. The corner positives reestablished at the center of the square formed by measuring record The corner position bearing and distance from each of the bearing trees. From the reestablished corner position:

A 14" western larch snag bears N6620W-46.9' with scribing visible on a partly healed blaze.

A 24" pon. pine stump bears  $S66^{\circ}W-52.1$ ' with a portion of the blaze visible. A 30" pon. pine stump bears  $S35^{\circ}E-34.9$ ' with scribing visible. A 17" western larch stump bears  $N64\frac{1}{2}$  E-44.7' with scribing visible on a partly

healed blaze.

## Description of monument and accessories I established to perpetuate the

original location of this corner:

Set a 2½" by 30" aluminum pipe with 2½" aluminum cap 24" in the ground and surrounded with a mound of earth and stone. Buried corner stone in the

new mound. From the new monument:

A 9" white fir bears N55½ E-16.2' scribed T9S R36E S12 BT.

A 9" western larch bears S52 E-35.5' scribed T9S R36E S13 BT.

A 7" pon. pine bears S 7½ W-21.0' scribed T9S R36E S14 BT.

A 7" lodgepole pine bears N 68½ W-15.1' scribed T9S R36E S11 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to the face of blaze. Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post North of corner and attached sign 54-9. Cap is marked:

Used steel tape and staff compass with 20°E declination, measured to the center of the bearing trees.

This corner was remonumented on October 8, 1985.

Witness: Willard Hulick.

REGISTERED PROFESSIONAL RCYBVRUR CHAJ

Wellin R. Wells

OREGON JULY 22, 1977 WILLIAM R. WELLS 1106

Office of County Sur	veyor County of Baker
State ofOregon, I hereby certify that the within instrument was filed in this offic	
for record on the day of	
	by
(COUNTY OFFICIA	

Form R6-7100-57 (9/71)

FILED 12-31-85 BAKER COUNTY SURVEYOR SURVEY NO. 9-36-80 ☆ GPO---798-276

T9S R36E

S1<u>1 | S</u>12

S14 | S13

1985 PLS 1106