History	٥f	original	corner	establishment:
MISTORY	OΤ	origina	COLLIE	09100114111110111

Ira L. Hoffman, U.S. Deputy Mineral Surveyor, under Mineral Survey No. 800 surveyed the Richard Woods claim known as Morning Star Lode from October 11,1917 to September 19, 1918 and approved by the U.S. Surveyor General's Office 19 November, 1918.

DIAGRAM T 98 R36E WM COR 4

Otis O. Gould, U.S. Deputy Surveyor did a dependent resurvey under special instructions dated 27 Nov. 1935, and approved 17 August, 1937.

SURVEYOR GENERAL'S RECORD STATES: (Otis O. Gould) Set an iron post, 3 ft. long, 1 in. diam., 27 in. in the ground with the marked stake deposited at the base, for Cor. No. 4, Horning Star lode, from which 4. with the brass cap marked A fir, 12 ins. diam., bears N17-45E, 10 lks. dist. marks grown over. (Old B.T.)

Description of corner syldence in und: bears N36E, 11 lks. dist. MS 800 1937 marks grown over. (Old B.T.)

B. MONUMENT FOUND:

I found a 2.5" dia. brass cap on a 1.0" dia. iron pipe 18" exposed in store mound under dead and down and rotted fir. U S GENERAL LAND OFFICE SURVEY The cap was marked: PENALTY \$250 FOR REMOVAL

ACCESSORIES FOUND:

4-MS 800 1937

Dead 13" dia. Grand Fir bears N3OE at 7.2 ft. with partly healed blaze and visible scribing. Sound 23" dia. Grand Fir bears N46E at 7.6 ft. with healed blaze.

Description of monument and accessories I established to perpetuate the original location of this corner:

CORNER WORK DONE ON 6/11/90

I removed the rotted fir and plumbed the monument to vertical in original f., hole in rock mound. Restacked rock mound to 5" exposure.

NEW ACCESSORIES ESTAPLISHED

A Grand Fir, 8" dia. bears N68E, 10.9 ft.; scribed CDR 4 MS 800 BT A Grand Fir, 20" dia. bears S32W, 26.7 ft., scribed CDR 4 MS 800 BT

Painted the blaze red on each BT

Painted a 6" wide red band around each BT

Placed brass washer marked "PLS 2060" at base of each BT blaze

Placed metal sign with bearing and distance information on each BT (54-3

Placed metal ATTENTION sign on each BT (54-4)

Placed 6 ft. steel fence post at corner with metal PROPERTY BOUNDARY sig and metal ATTENTION sign (54-2 and 54-4) attached

I measured to the centerline of each bearing tree using tape and hand compass with declination set at 20 degrees east.

REGISTERED

PROFESSIONAL LAND SURVEYOR

OREGON. JULY 15, EDWIN A. STRYKER

Office of...... County of..... State of....... ! hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... by (DEPUTY) (COUNTY OFFICIAL)

Form R6-7100-57 (9/71)

+GPO--591-971, 1988

11-16-1990

The Control Bond Con SUSPET NO 9-36-118