والأربو بقديق فالوقوق والوجوي المعتلة لأعوام حريات المقاصمين البياني المدوم فجح شفيها المعام الأالحال مالمات

Z-11

dist. marked 1/4 S BT.

<u>History of original corner establishment:</u> Corner was originally established in 1881 DIAGRAM by Eugene P. McCormack, under General Land Office Contract Number 398. Surveyor T9S R37E General's Notes state: **S33** Set Post 3 ft. long 3 ins. square 24 ins. in the ground for 1/4 sec. cor. marked 1/4 S 1/4 ---S 4 on N face from which: T10s 1971 A pine 24 ins. diam. bears N40°E, 51 lks. (BLM CAP)

dist. marked 1/4 S BT. In 1971 Owen C. Chatters II, Cadastral Surveyor for the BLM remonumented this corner under Special Instructions dated May 3, 1957, Group 350. BLM records states: The 1/4 sec. cor. of secs. 4 and 34, determined at record bearing and distance from the remains of the determined at record bearing and distance from the remains of the original bearing trees: A pine stump, 36 ins. diam., bears S65°E., 30 lks. dist., with scribe marks 1/4 S BT visible on open blaze. At the corner point, set an iron post, 28 ins. long, 2½ ins. diam., 24 ins. in the ground, with brass cap mkd. (SEE DIAGRAM) from which new bearing trees: A ponderosa pine, 14 ins. diam., bears N19°E, 31 lks. dist., mkd 1/4 S33 BT. A larch, 11 ins. diam., bears S57°E, 33 lks. dist., mkd. 1/4 S4 BT. Deposit a granite stone, 10x8x4 ins., mkd. X, and broken glass alongside iron post. Corner is located 18 lks. E. of mining ditch drains SF

mining ditch, drains SE.

Description of corner evidence found:

A pine 36 ins. diam. bears S65°E, 30 lks.

Found 2%" iron post with a 3%" brass cap stamped as shown in diagram. Monument is projecting 4 inches out of the ground. Monument is solid and in good condition.

Ponderosa Pine, 16" dia, healed blaze, bears N18°32'E, 20.19 ft. Established by the BLM (Rec: N19°E, 20.46 ft.)

Western Larch, 12" dia, healed blaze, bears S58°08'E, 22.30 ft. Established by the BLM (Rec: S57°E, 21.78 ft.)

Measurements to existing BT's taken with an Electronic Tacheometer with bearings based on the survey control network.

Description of monument and accessories I established to perpetuate the original location of this corner:

No work is needed on the monument. From Which:

A Ponderosa Pine, 11" in dia, bears N52°15'W, 30.2 ft, scribed: 1/4 S33 BT A Ponderosa Pine, 12" in dia, bears S61°45'W, 24.6 ft, scribed: 1/4 S4 BT

Nailed a brass washer stamped PLS 848 on blaze above BT scribe as taken this survey. Nailed Bearing Tree (54-3) signs above blaze and Land Survey Monument (54-9) signs on back of each tree as required. Painted a 6" red band above Bearing Trees signs. Measurements to BT's taken with a magnetic compass, declination 20° East, and a nylon clad steel tape. Set steel fence post with Land Survey Monument (54-9) sign 5' north of the monument.

REGISTERED PROFESSIONAL LANDERVEYOR OREGON JULY 12, 1888 DOUGLAS M. FERGUSON 8 4 8

This work is performed by: Douglas M. Ferguson PLS 848 Witnessed by: D.Mitchell Ferguson & Rick Saul April 1, 1991 Refer to Baker Co. Survey No. 9-37-181

Office of Countries of I hereby certify that the in this office for record on the date by	nty of	ment was filed — FILED <u> - とと-らと</u>
(COUNTY OFFICIAL)	(DEPUTY)	BAKER COUNTY SURVEYOR

SURVEY NO. 4-3/