



- LEGEND**
- Found $\frac{3}{8}$ " rebar.
 - Set $\frac{3}{8}$ " x 30" rebar with yellow plastic cap mkt. HANLEY, ENGR PLS 1206
 - () Record of original plat.

SURVEY NARRATIVE

This survey was performed at the request of P.O.P. General Contractors for the purpose of monumenting a parcel in Block 9, Mix Addition to Baker, Oregon. The entire block was under single ownership at the time of this survey which segregates the smaller parcel from the remainder of Block 1. Survey monuments were relocated from previous survey work as shown on this plat and the block subdivided in the prescribed manner.

MAP OF SURVEY
 IN BLOCK 9, MIX ADDITION TO
 BAKER, OREGON
 Surveyed Oct. 20, 1982 Scale 1"=50'
 For P.O.P. General Contractors

**REGISTERED
 PROFESSIONAL
 LAND SURVEYOR**

William L. Hanley

OREGON
 JULY 14, 1978
 WILLIAM L. HANLEY
 1639

FILED Oct. 26, 1982

BAKER COUNTY SURVEYOR
 SURVEY NO. 9-40-197