



**REFERENCE**

Survey No. 9-40-70BC  
 Filed March 3, 1976, by  
 J. D. Hanley.

**LEGEND**

- Found 5/8" x 30" rebar with yellow plastic cap marked HANLEY ENGR. PLS 1206
  - Monument of record - Survey No. 9-40-70BC - not found.
  - Set 5/8" x 30" rebar with yellow plastic cap marked B. HANLEY SURV. ORLS 1639
- [ ] Record of Survey No. 9-40-70BC.

**SURVEY NARRATIVE**

THIS SURVEY WAS PERFORMED AT THE REQUEST OF DAVE STILL, LANDOWNER, FOR THE PURPOSE OF SEGREGATING THE PARCEL SHOWN ON THIS PLAT FROM THE SURROUNDING PROPERTY. THE BASIS OF THIS SURVEY IS SURVEY NO. 9-40-70BC FILED MARCH 3, 1976, AND THE RECOVERED MONUMENTATION AS SHOWN. PROPER PROFESSIONAL AND STATUTORY METHODS WERE USED IN THE PERFORMANCE OF THIS SURVEY.

**MAP OF SURVEY**

IN THE S 1/2 SW 1/4 SECTION 20, T. 9 S., R. 40 E., W.M.

Surveyed Sept. 03, 1985

Scale 1"=100'

FOR DAVE STILL FILED 11-26-85

BAKER COUNTY SURVEYOR

SURVEY NO. 9-40-235

REGISTERED  
 PROFESSIONAL  
 LAND SURVEYOR

William L. Hanley  
 BAKER, ORE.

OREGON  
 JULY 14, 1978  
 WILLIAM L. HANLEY  
 1639