#4 REBAR IN BOX
PUNCH MARK IN CONCRETE PAD
SCRATCH MARK IN STEEL
SITE
#5 REBAR YELLOW CAP PLS 2162 IN BOX
#4 REBAR IN BOX
#5 REBAR IN BOX
#5 REBAR IN BOX
#5 REBAR IN BOX
AUBURN AVE.
31.43
42.46
54.52
48.35
38.08
59.02
49.49
46.96
47.09
50.60
64.33
46.05
47.53
41.72
68.77
64.20
46.41
46.57
83.79
78.99
40.26
39.45
47.07
37.70
42.34
29.86
34.09
21.74
26.04
81.04
SITE
1/4 Corner
50.80
62.75
88.41
82.98
TACK IN WINDOW SILL
13TH STREET
12TH STREET
11TH STREET
10TH STREET
9TH STREET
SITE
SITE
SITE
SITE
PLACE
STREET

COMMENTS

This survey was made to preserve the chain of evidence for the existing monuments removed during street construction. Although these are all generally accepted control points, this survey in no way makes any judgement as to their origin or meaning.

REGISTERED PROFESSIONAL LAND SURVEYOR
Gary Van Patten
OREGON
JULY 26, 1985
GARY VAN PATTEN
2162

FILED Sept 30, 1988
BAKER COUNTY SURVEYOR
SURVEY NO. 9-40-7TE

LEGEND

- Nail & Flasher
- Point as described
- Hub & Tack
- Set #5 x 30" rebar with yellow cap marked CITY OF BAKER PLS 2162
- Existing monument before construction

CITY OF BAKER, OREGON
OFFICE OF TECHNICAL SERVICES

AUBURN AVE. MONUMENTS 9TH ST. — 13TH ST. REFERENCES & REPLACEMENT

DRAWN G.V.P. APPROVED City Engineer
CHECKED APPROVED City Manager
SCALE N.T.S.
DATE Sept. 1988
SHEET 1 OF 1 SHEETS