CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

This corner was originally established by W.B. Barr, U.S Deputy Surveyor, under his Contract No. 492, dated August 22, 1883, during April, 1884. The original notes state that at the corner a 14"by12"by10" marked basalt stone was set 9" in the ground from which:

A 12" pine bears N60°E-94 lks, scribed 1/4S BT. A 8" juniper bears S20°E-19 lks, scribed 1/4S BT.

	N -2	23	
DIA	GRAM		
T1	0S	R35∄E	
<u>1</u> 4	-	13 	
	<i>\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\\</i>	~ <i>~</i>	

Description of corner evidence found:

A 22" pon. pine bears $N63\frac{1}{2}$ °E-62.0' with scribing visible on partly healed double blazes. A 11" juniper bears S20°E-12.5' with scribing visible on open double blazes.

The corner location was reestablished by measuring record distance from each of the found bearing trees.

Description of monument and accessories I established to perpetuate the

original location of this corner:

Set a $2\frac{1}{2}$ " by 30 " aluminum pipe with $2\frac{1}{2}$ " aluminum cap 100" in the ground to rock and surrounded with a mound of earth and stone from wh

Attached sign 54-3 and 54-9 and painted face of blaze and a 6" red band around each bearing tree. Set steel fence post East of corner and attached sign 54-9. Cap is marked:

Used steel tape and staff compass with 20° E declination, measured to the center of the bearing trees.

This corner was remonumented on October 22, 1985.

Witness: Willard Hulick.

T1 OS R35 &E S1 3 S24 1985 PLS 1106

REGISTERED PROFESSIONAL LAND SURVEYOR

Willi R. Wells OREGON JULY 22, 1977 WILLIAM R. WELLS

1106

County Surveyor Eaker County of State of Oregon, I hereby certify that the within instrument was filed in this office for record on the...... day of...... , 19..... (COUNTY OFFICIAL) (DEPUTY)

Form R6-7100-57 (9/71)

\$U.S. GOVERNMENT PRINTING OFFICE - 1983-793-276

FILED 2-3-86 DAKER COUNTY SURVEYOR SURVEY NO. 10-352-100