## CERTIFIED RECORD OF LAND CORNER MONUMENTATION

History of original corner establishment:

None.

DIAGRAM T10S R36E C-N-SE 1/64 S 17

No evidence of corner establishment found in County Records.

Description of corner evidence found:

None.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set a  $2\frac{1}{2}$ " by 30" aluminum pipe with  $2\frac{1}{2}$ " aluminum cap, 25" in the ground and surrounded with a mound of earth and stone, from which:

A 7" Lodgepole Pine bears S  $41\frac{1}{2}$ ° E - 21.1', scribed: C-N-SE 1/64 S17 BT.

A 7" Lodgepole Pine bears S 10° W - 36.31, scribed: C-N-SE 1/64 S17 BT.

New bearing trees have a brass washer stamped PLS 1106 nailed to face of blaze. Attached sign 54-3 and 54-9, and painted face of blaze and a 6 red band around each bearing tree.

Set steel fence posts West and South of corner, and attached sign 54-9 to one post, and sign 54-2 to both posts.

Used steel tape and staff compass with  $20^{\circ}\text{E}$  declination, measured to the center of the bearing trees.

|   |  | •                                |
|---|--|----------------------------------|
| This corner was monumented on May 13, 1986. |  | Cap is marked:                   |
| Witnessed by: Willard Hulick.               | REGISTERED PROFESSIONAL LAND SURVEYOR      | T10S R36E<br>C-N-SE 1/64<br>S 17 |
|   | Willi R. Wells                             | 1986                             |
|   | OREGON JULY 22, 1977 WILLIAM R. WELLS 1106 | PLS 1106                         |
| Office of County Surveyor                   | County of Baker                            | ed in this office                |
| for record on the day of                    |  |                                  |
| (COUNTY OFFICIAL)                           | by   |                                  |
|   |  |                                  |

Form R6-7100-57 (9/71)

☆U,S. GOVERNMENT PRINTING OFFICE - 1983-793-276

BAKER COUNTY SURVEYOR
SURVEY NO. 10-36-46