

MONUMENTATION

See standard U.S.F.S. "INDEX NO.", in the circle below and on the corresponding circle on the Map. Refer to "CERTIFIED RECORD OF LAND CORNER MONUMENTATION" form, as referenced to this Map of Survey and filed in the office of the County Surveyor. Those forms give complete details as to the history, pertaining to these corners as well as, complete information as to the evidence found, the method of establishment, description of monuments set & accessories established. Monumentation basically consists of the following: Monuments as shown in the LEGEND are stamped as shown below. Bearing Trees are established as shown below, with Bearing Tree signs nailed above the blaze, Warning signs nailed on the back, brass washers stamped PLS 848 nailed on the blaze above the BT scribing & painted a 6" red band around each tree. Where Bearing Trees are not available 5/8" x 30" iron pins with plastic caps marked PLS 848 & guard post with Bearing Tree & Warning signs are set as shown. Set steel post with warning and/or boundary signs on the property line, each way from property corner & within 5 ft. in a cardinal direction from controlling corners. Magnetic compass should be used in this area for approximations only, use true bearing for re-establishment of corners.

TIOS R36E
S33
1988
PLS 848
Lodgepole Pine 6" dia, Bears N4°15'E, 14.5 ft, scribed W/6 S38 BT
Lodgepole Pine 6" dia, Bears S7°13'E, 22.7 ft, " W/6 S33 BT

TIOS R36E
S33
1988
PLS 848
Set iron pins as described above as follows: N45°00'W, 10.0 ft, N45°E, 10.0 ft, S45°E, 10.0 ft, S45°W, 10.0 ft

TIOS R36E
S33
1988
PLS 848
Set iron pin as described above as follows: S0°13'W, 10.0 ft, N89°41'E, 10.0 ft

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 20" dia, Bears N8°36'W, 42.8 ft, scribed TIOS R36E S27 BT
Ponderosa Pine 18" dia, Bears N6°46'E, 129.6 ft, " S26 BT
Ponderosa Pine 20" dia, Bears S49°30'E, 74.2 ft, " S33 BT
Ponderosa Pine 22" dia, Bears S39°22'W, 169.8 ft, " S34 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 12" dia, Bears N56°25'E, 33.2 ft, scribed C-W-NE/256 S34 BT
Ponderosa Pine 12" dia, Bears N86°58'W, 58.8 ft, " C-W-NE/256 S34 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 14" dia, Bears N57°39'E, 48.0 ft, scribed C-N/16 S34 BT
Ponderosa Pine 12" dia, Bears S22°58'W, 40.7 ft, " C-N/16 S34 BT

TIOS R36E
S33
1988
PLS 848
Western Larch 12" dia, Bears S33°36'W, 53.3 ft, scribed C-N/16 S33 BT
Lodgepole Pine 8" dia, Bears N38°17'E, 50.0 ft, " C-N/16 S33 BT

TIOS R36E
S33
1988
PLS 848
Lodgepole Pine 8" dia, Bears S8°46'W, 6.6 ft, scribed NW 1/6 S33 BT
White Fir 10" dia, Bears N72°46'E, 20.6 ft, " NW 1/6 S33 BT

TIOS R36E
S33
1988
PLS 848
Western Larch 8" dia, Bears S82°23'E, 24.8 ft, scribed C-S-N/64 S33 BT
Lodgepole Pine 10" dia, Bears S 3°22'W, 27.0 ft, " C-S-N/64 S33 BT

TIOS R36E
S33
1988
PLS 848
Western Larch 10" dia, Bears S59°04'W, 24.6 ft, scribed SW-NE/64 S33 BT
Lodgepole Pine 12" dia, Bears N84°00'E, 14.0 ft, " SW-NE/64 S33 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 12" dia, Bears S82°34'W, 51.2 ft, scribed V4 S35 BT
Ponderosa Pine 12" dia, Bears S65°41'E, 88.2 ft, " 1/4 S36 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 20" dia, Bears N81°20'E, 17.6 ft, scribed C/4 S35 BT
Ponderosa Pine 12" dia, Bears S36°58'W, 42.7 ft, " C/4 S35 BT

TIOS R36E
S33
1988
PLS 848
Set iron pins as described above as follows: S0°20'W, 10.0 ft, S89°47'W, 10.0 ft

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 14" dia, Bears S33°34'E, 22.3 ft, scribed C-W-NE/256 S34 BT
Ponderosa Pine 12" dia, Bears N81°52'E, 44.2 ft, " C-W-NE/256 S34 BT

TIOS R36E
S33
1988
PLS 848
Set iron pin as described above as follows: N0°30'E, 31.5 ft, S89°05'E, 31.6 ft

TIOS R36E
S33
1988
PLS 848
Set iron pin as described above as follows: N89°57'W, 10.1 ft, S0°00'W, 10.1 ft

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 12" dia, Bears S57°54'W, 39.6 ft, scribed C-W-E/64 S33 BT
Lodgepole Pine 8" dia, Bears N37°57'W, 19.0 ft, " C-W-E/64 S33 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 6" dia, Bears N9°28'E, 14.8 ft, scribed C/4 S33 BT
Ponderosa Pine 6" dia, Bears S63°26'W, 7.8 ft, " C/4 S33 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 12" dia, Bears N80°21'E, 36.6 ft, scribed S/16 S34 BT
Ponderosa Pine 14" dia, Bears S89°56'W, 39.7 ft, " S/16 S33 BT

TIOS R36E
S33
1988
PLS 848
Set iron pin as described above as follows: S89°44'W, 10.0 ft, S0°11'W, 10.0 ft

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 16" dia, Bears S63°00'W, 41.0 ft, scribed S/16 S34 BT
Ponderosa Pine 20" dia, Bears N19°24'E, 37.8 ft, " S/16 S35 BT

TIOS R36E
S33
1988
PLS 848
Set iron pin as described above as follows: N0°12'E, 63.7 ft, N89°55'W, 60.9 ft

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 16" dia, Bears N61°17'E, 29.1 ft, scribed E/16 S34 BT
Ponderosa Pine 10" dia, Bears N40°15'W, 63.7 ft, " E/16 S34 BT

TIOS R36E
S33
1988
PLS 848
Ponderosa Pine 6" dia, Bears N19°24'W, 8.9 ft, scribed W/16 S34 BT
Ponderosa Pine 6" dia, Bears N56°57'W, 30.9 ft, " W/16 S34 BT

CORNER MAINTENANCE

Found brass cap monument stamped as shown. Repaired Monument & accessories as shown

TIOS R36E
S33
1974
No repair is needed at the corner monument (bearing trees).
Western Larch 8" dia, Bears S79°57'E, 38.6 ft, scribed S33 BT
Western Larch 10" dia, Bears S55°01'W, 38.8 ft, " S32 BT
White Fir 8" dia, Bears N29°25'W, 32.7 ft, " S29 BT
Painted a 6" red band at breast ht. around the

TIOS R36E
S33
1974
No repair is needed at corner monument. For new access, set a 5/8" x 30" iron pin with plastic cap marked 848. B guard post with bearing tree and warning sign, 10 ft. Painted a 6" red band at breast ht. around the sec.

TIOS R36E
S33
1974
No work is required at corner monument. Painted band at breast ht. around the bearing trees (the Bureau of Land Management).

TIOS R36E
S33
1974
No work is required at corner monument. Painted band at breast ht. around the bearing trees taken by B.L.M.

TIOS R36E
S33
1974
No work is needed at monument (New Bear).
Western Larch 14" dia, Bears N30°54'E, 11.0 ft, scribed V4 S33 BT
Painted a 6" red band at breast ht. around the

TIOS R36E
S33
1974
Reconstructed mound of stone around cap pipe.
Painted a 6" red band at breast ht. around trees taken by B.L.M.

TIOS R36E
S33
1974
Reconstructed mound of stone around cap pipe. Trees taken by B.L.M. have proper signs a 6" red band at breast ht.

TIOS R36E
S33
1974
Reconstructed mound of stone around cap pipe (New Bearing Trees).
Lodgepole Pine 10" dia, Bears N50°30'W, scribed TIOS R36E S34 BT
Ponderosa Pine 10" dia, Bears N80°25'E, " S35 BT

TIOS R36E
S33
1974
Corner monument in good condition, no repair. Painted a 6" red band at breast ht. around the bearing tree as B.L.M. & the original tree as noted. B used by the B.L.M.

TIOS R36E
S33
1974
No repair work is required at the corner. Painted a 6" red band at breast ht. around the bearing trees (B.L.M.)

