CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. R-4
History of original corner establishment:

Baker County Survey Records show no previous establishment of this Cor.

DIAGRAM

T108 R36E S19 E1/16-.-S30 1988 FLS 848

Description of corner evidence found:

Baker County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set $2-1/2"\times30"$ aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 27" in the ground. From Which:

A Ponderosa Pine 16" dia.,Bears $N32^0$ 46'W., 11.5 ft.,scribed: E1/16 S19 BT A Ponderosa Pine 10" dia.,Bears S 1^0 20'E., 14.0 ft.,scribed: E1/16 S30 BT Measurements to trees taken with Electronic Tacheometer with bearings turned from the survey control network.

Nailed a brass washer stamped FLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North & South 5 ft. from the corner.

PROFESSIONAL LAND SURVEYOR	
Mark	
OREGON JULY 12, 1559 MOUNTAS M. FERGUSON 848	

This work is performed by:
Douglas M. Ferguson PLS 848
Mt.Vernon Oregon.
On: Nov. 17, 1988
Refer to Map of Survey No. 10-36-64
Witnesses: D.Mitchell Ferguson & Ken Delano

Office of	County of	
State of, I hereby certify that the within instrument was filed in this office		
for record on the day of	, 19	
bý		
(COUNTY OFFICIAL)	(DEPUTY)	

Form R6-7100-57 (9/71)

BAKER COUNTY SURVEYOR
SURVEY NO. 10 - 36 - 86