CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. X-11
History of original corner establishment:

Baker County Survey Records show no previous establishment of this Cor.

DIAGRAM

T10S R36E C 1/4 S33 1988 PLS 848

Description of corner evidence found:

Baker County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set $2-1/2"\times30"$ aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the **DIAGRAM**, SET 10" in the ground and raised a mound of stone around the pipe.

From Which:

Ponderosa Pine 6"dia.,Bears N 9° 28'E.,14.8ft.,scribed: C1/4 S33 BT Ponderosa Pine 6"dia.,Bears S63 $^{\circ}$ 26'W., 7.8ft.,scribed: C1/4 S33 BT Measurements to trees taken with Electronic Tacheometer with bearings turned from the survey control network.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Fainted a 6" red band at breast ht. around each tree. Set steel fence post with warning Sign, North 4 ft. from the corner.

REGISTERED PROFESSIONAL LAND SURVEYOR

OREGON JULY 12, 1969 DOUGLAS M. FERGUSON 848 This work is performed by:
Douglas M. Ferguson PLS 848
Mt.Vernon Oregon.
On: Sept. 14, 1988
Refer to Map of Survey No. 10-36-61
Witnesses: D.Mitchell Ferguson & Ken Delano

Office of	County of
State of , /	hereby certify that the within instrument was filed in this office
for record on the day of	, 19
	by
(COUNTY OFFICIAL)	

Form R6-7100-57 (9/71)

GPO---791-311

BAKER COUNTY SURVEYOR
SURVEY NO. 10-36-141