CERTIFIED RECORD OF LAND CORNER MONUMENTATION

TNDEX No. $\chi - 15$ History of original corner establishment:

Baker County Survey Records show no previous establishment of this Cor.

DIAGRAM

T105 R36E C 1/4 S34 198B PLS 848

Description of corner evidence found:

Baker County Survey Records show no previous establishment of this Cor.

Description of monument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the <code>DIAGRAM</code>, SET 29" in the ground.

From Which:

Set 5/8"x30" iron pins with plastic caps stamped: PLS 848, and guard posts with Warning and Bearing Tree Signs as follows: N10⁰30'E., 31.5 ft, in County Road Right of Way fence. S85⁰05'E., 31.6 ft, in County Road Right of Way fence. Measurements to pins taken with Electronic Tacheometer with bearings turned from the survey control network.

| PROFESSIONAL LAND SURVEYOR | |
|---|--|
| What - | |
| OREGON JULY 12 1200 DOUGLAS M. FERGUSON 848 | |

REGISTERED

This work is performed by:
Douglas M. Ferguson PLS 848
Mt.Vernon Dregon.
On: Sept. 8, 1988
Refer to Map of Survey No. 10-36-61
Witnesses: D.Mitchell Ferguson & Ken Delano

| Office of | County of | | |
|---|-----------|--|--|
| State of , I hereby certify that the within instrument was filed in this office | | | |
| for record on the day of | | | |
| by | | | |
| (COUNTY OFFICIAL) | (DEPUTY) | | |

Form R6-7100-57 (9/71)

GPO--791-311

| FILED_ | 3-30 | -89 |
|--------|------|----------|
| | | SURVEYOR |
| | | -36-144 |