CERTIFIED RECORD OF LAND CORNER MONUMENTATION

INDEX No. Z-16 History of original corner establishment:

Baker County Survey Records show no previous establishment of this Cor.

DIAGRAM

T105 R36E E1/16 S34 T115 1988 PLS 848

Description of corner evidence found:

Baker County Survey Records show no previous establishment of this Cor.

Description of manument and accessories I established to perpetuate the original location of this corner:

Set 2-1/2"x30" aluminum pipe with 3-1/2" aluminum cap, stamped as shown on the DIAGRAM, SET 28" in the ground.

From Which:

Ponderosa Pine 16" dia., Bears $N61^{O}17'E.$, 29.1 ft., scribed: E1/16 S34 BT Ponderosa Pine 10" dia., Bears $N40^{O}15'W.$, 63.7 ft., scribed: E1/16 S34 BT Measurements to trees taken with Electronic Tacheometer with bearings

turned from the survey control network.

Nailed a brass washer stamped PLS 848 on blaze above BT scribe, Bearing Tree Sign above blaze, and warning sign on back of each tree. Painted scribe, Bearing a 6" red band at breast ht. around each tree. Set steel fence posts with warning & Boundary Signs, North 4 ft. and East 3 ft. from the corner.

REGISTERED PROFESSIONAL AND SURVEYOR

OREGON JULY 12. 1258 DOUGLAS M. FERGUSON 848

This work is performed by: Douglas M. Ferguson PLS 848 Mt. Vernon Oregon.

On: Sept. 9, 1988

Refer to Map of Survey No. 10-36-61 Witnesses: D.Mitchell Ferguson & Ken Delano

Office of	County of
State of	I hereby certify that the within instrument was filed in this office
for record on the day of	

(COUNTY OFFICIAL	

Form R6-7100-57 (9/71)

GPO-791-311

FILED 3- 30-89 BAKER COUNTY SURVEYOR SURVEY NO. 10-36-157